



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7557Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	TO REPAIR SEE LABOUR	2,147.90	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,768.30	-
1	ROCKER COVER GARNISH LH	CUT	290.00	290.00
1	REAR FENDER GARNISH LH	NOT NECESSARY	173.60	-
	LESS 20% DISCOUNT		-875.96	-58.00
			3,503.84	232.00
	<u>SPECIAL NETT ITEMS</u>			
1	RR DOOR COMFORTDELGRO LOGO STICKER LH (SN)	NECESSARY	80.00	80.00
1	REAR FENDER "PETROL ONLY" STICKER (SN)	NECESSARY	15.00	15.00
1	ADVERTISEMENT LOGO (SN)	NECESSARY	200.00	200.00
			295.00	295.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND REAR FENDER LH.		1,100.00	700.00
	SPRAY PAINTING CHARGE.		1,000.00	750.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
			2,280.00	1,450.00
	GRAND TOTAL		6,078.84	1,977.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,550.00

Report Ref No. NS/INC22010620/Gqce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.