

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22010629/UVY3Q2  
**Date:** 15/11/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00141202200
Claimant Vehicle No :	SKK119D	Insured Vehicle No :	SKS9495R
Date of Loss:	25/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207636/C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK119D		
Make & Model:	MINI COOPER, 1.5 HATCHBACK 3DR LED DSC (A)	Engine No:	F6391137B48A20A
Reg. Date:	01/07/2015 (Man. Year: 2015)	Chassis No:	WMWXM720702A77171
Colour:	Red	Odometer:	153641 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/40 R18	Rear Tyre Size:	215/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,066.75	2,440.30	6,626.45	73.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,120.00	2,820.00	71.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,006.75</b>	<b>3,560.30</b>	<b>9,446.45</b>	<b>72.63</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,006.75</b>	<b>2,800.00</b>	<b>10,206.75</b>	<b>78.47</b>

### INSPECTION

Date of Assignment:	26/10/2022	
Date Inspected:	27/10/2022	Inspected At:
Estimated Period of Repair:	4.0 days	130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 Repairer:Zoom Autowerks Pte Ltd (HQ)

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2022)

**Parts:** 144 MINI COOPER 1.5 HATCHBACK 3DR LED DSC (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKK119D)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	755.00 FL	*- FL
2	1		*FRONT BUMPER SIDE ARCH GARNISH (N/S)	Grazed	185.00 FL	*185.00 FL
3	1		*FRONT BUMPER SIDE RETAINER (N/S)	Necessary	58.00 FL	*58.00 FL
4	2		*FRONT FENDERS	No such part	1,070.00 FL	*- FL
5	2		*FRONT FENDER INNER SHIELDS	Not Necessary	330.00 FL	*- FL
6	1		*FRONT WHEEL ARCH GARNISHES	N/S Grazed	440.00 FL	*220.00 FL
7	1		*FRONT WHEEL HUB (O/S)	Damaged	195.00 FL	*195.00 FL
8	1		*FRONT WHEEL BEARING (O/S)	Damaged	172.00 FL	*172.00 FL
9	1		*FRONT SHOCK ABSORBER (O/S)	Bent	385.00 FL	*385.00 FL
10	1		*FRONT KNUCKLE ARM (O/S)	Warped	459.00 FL	*459.00 FL
11	1		*FRONT LOWER ARM (O/S)	Not Necessary	516.00 FL	*- FL
12	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
13	2		*FRONT TYRES	Serviceable	1,000.00 FS	*- FS
14	1		*FRONT WHEEL RIMS	O/S Warped	2,100.00 FS	*800.00 FS
15	1		*REAR TYRE	Not Necessary	500.00 FS	*- FS
16	1		*REAR WHEEL RIM	Not Necessary	1,050.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,295.00</b>	<b>2,524.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	228.25	83.70
<b>Total Parts (\$\$)</b>	<b>9,066.75</b>	<b>2,440.30</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	500.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	100.00
4	TO APPLY UNDERCOATING	New	80.00	0.00
5	PANEL BEATING	New	1,600.00	480.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,940.00</b>	<b>1,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >