

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010633/EVY3Q2**Date:** 05/01/2023**REFERENCE**

Insured/Claimant: CHAN XUAN HAO Policy No: DMPCSNW00079232200

Date of Loss: 20/10/2022 Nature of Claim: OD Claim No: SNM22D207584/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMT1740G**

Make & Model: JAGUAR E-PACE, 2.0 S (A)

Engine No: 190327Y0217PT204

Reg. Date: 30/03/2020 (Man. Year: 2019)

Chassis No: SADFA2AX8K1Z64331

Colour: Grey

Odometer: 35828 km

Engine Capacity: 1997 cc

Market Value/New Car Price: S\$160,000.00

Price:

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm

Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,199.54	9,337.41	862.13	8.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,728.00	5,128.00	2,600.00	33.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,927.54	14,465.41	3,462.13	19.31
- Excess (\$\$)	750.00	750.00	0.00	0.00
(\$\$)	17,177.54	13,715.41	3,462.13	20.15
+ GST 7.00/7.00% (\$\$)	1,202.43	960.08	242.35	20.16
Nett Amount (\$\$)	18,379.97	14,675.49	3,704.48	20.15

INSPECTION

Date of Assignment: 26/10/2022

Date Inspected: 28/10/2022 Inspected At:

45 LENG KEE ROAD

SINGAPORE 159103

Repairer:Wearnes Automotive Pte Ltd (Leng Kee)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	M1-SUV	JAGUAR E-PACE 2.0 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT1740G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -BUMPER FRT	Crushed	1,694.80 FS	*1,525.32 FS
2	1		*MESH-GRILLE LH	Cut	226.10 FS	*209.61 FS
3	1		*PANEL -AIR DUCT BLANK	Broken	66.40 FS	*59.76 FS
4	1		*HEADLAMP LH	Cut	6,073.60 FS	*5,466.24 FS
5	1		*MOULDING LH	Crushed	340.80 FS	*315.99 FS
6	1		*BRACKET -BUMPER LH	Not Necessary	31.20 FS	*- FS
7	1		*PLATE -BLANKING LH	Crushed	84.90 FS	*78.75 FS
8	1		*CTR BRACKET -BUMPER	Broken	200.52 FS	*200.52 FS
9	1		*GRILLE -RADIATOR	Broken	580.23 FS	*580.23 FS
10	1		*SURROUND -RAD GRILLE	Broken	821.88 FS	*821.88 FS
11	2		*PIN -LOCATING	Necessary	20.88 FS	*20.88 FS
12	1		*HL MOUNTING -BRACKET	Necessary	58.23 FS	*58.23 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,199.54	9,337.41
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER ,HEADLAMP LH, FENDER MOULDING,BUMPER FRT MOULDING LH	New	3,900.00	1,300.00
2	TO SPRAYPAINT ON FRT BUMPER ,BONNET,FRT LH FENDER ,ETC	New	3,000.00	3,000.00
3	TO FOCUS HEADLAMP	New	207.00	207.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
Gross Labour Cost (\$\$)			7,728.00	5,128.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >