

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010634/ANY3Q2**Date:** 19/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00014582200
<b>Claimant Vehicle No :</b>	SMR8101R	<b>Insured Vehicle No :</b>	SNB4334J
Date of Loss:	09/10/2022	Nature of Claim: TP	Claim No: SNM22D207643/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMR8101R</b>		
Make & Model:	BMW 116D, 1.5 D 5DR HATCH DSC LED (A)	Engine No:	31229567B37D15A
Reg. Date:	08/08/2016 (Man. Year: 2016)	Chassis No:	WBA1V72050V724584
Colour:	Silver	Odometer:	73147 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,560.00	800.00	2,760.00	77.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	680.00	920.00	57.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,160.00</b>	<b>1,480.00</b>	<b>3,680.00</b>	<b>71.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,160.00</b>	<b>1,150.00</b>	<b>4,010.00</b>	<b>77.71</b>

**INSPECTION**

Date of Assignment:	27/10/2022		1 KAKI BUKIT AVENUE 6
Date Inspected:	28/10/2022	Inspected At:	#02-11 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	2.0 days		Repairer: Automobile Hub Enterprise

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2023)
Parts:	144	BMW 116D 1.5 D 5DR HATCH DSC LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR8101R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FENDER	Repair	1,562.00 F	*- FL
2	1		*REAR LH WHEEL RIM	Cut	1,200.00 FS	*800.00 FS
3	1		*ROCKER PANEL OUTER SKIRTING LH	Repair	798.00 F	*- FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					3,560.00	800.00
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	0.00
Total Parts (S\$)					3,560.00	800.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	600.00	200.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	0.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >