

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0410/22

DATE : 20-OCT-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR LOW YIN SHEN
ADDRESS : BLK 133 BEDOK NORTH AVE 3
#12-122
S(460133)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 7220096990
VEHICLE NO : SNG6374D
MODEL CODE : TDZARBWJ12U3AA----
MODEL/YEAR : NISSAN QASHQAI 1.3T MHEV PRESTIGE 2-TONE MY2022
ENGINE NO : HR13430239A
CHASSIS NO : SJNTAAJ12U1085709
MILEAGE : 3876 KM
DATE IN : 20/10/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 20/10/2022

- 9645 0084 e/mu@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNG6374D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RADIATOR SUPPORT RENEW FRT BUMPER	840.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	500.00	
3	ZZ/003	REMOVE AND INSTALL BOTH HEADLAMP AND FOCUS REPLACE IF DAMAGE	48.00	
4	ZZ/004	REMOVE AND INSTALL FRT BUMPER SENSOR AND INNER BRACKET	110.00	
5	ZZ/005	SUPPLY FRT LICENSE PLATE		
6	ZZ/006	COMPUTER CHECK DIAGNOSIS	180.00	
TOTAL LABOUR CHARGES			1678.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNG6374D

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMAR
1	FRT LH FENDER WHEEL ARC MOULDING	63811-6UA0A	584.20	
2	RADIATOR GRILLE TOP MOULDING	62322-6UA0A	484.40	
3	SHUTTER ASSY-RADIATOR GRILLE	21421-6UA0A		453.00
4	GRILLE-RADIATOR	62310-6UA2A	812.70	
5	CLIP FRT BUMPER @ SGD\$1.40 EACH	01553-05933	14.00	
6	SUNDRIES	NPN		50.00
7	LH HEADLAMP MOULDING	62415-6UA0B	170.50	
8	RH HEADLAMP MOULDING	62414-6UA0B	170.50	
9	LH SIDE BRACKET FRT BUMPER	62223-6UA0A	25.20	
10	RH SIDE BRACKET FRT BUMPER	62222-6UA0A	25.20	
11	UPPER REINFORCEMENT FRT BUMPER	F2030-6UAMH	694.80	
12	UPPER ENERGY ABSORBER FRT BUMPER	62090-6UA5A	294.60	
13	LOWER REINFORCEMENT FRT BUMPER	F2031-6UAEH	746.20	
14	ENERGY ABSORBER FRT BUMPER	62091-6UA0A	99.30	
15	RH SIDE FRT BUMPER GRILLE FINISHER	62252-6UA0A	64.40	
16	LH SIDE FRT BUMPER GRILLE FINISHER	62253-6UA0A	64.40	
17	TOW HOOK COVER FRT BUMPER	622A0-6UA0H	24.90	
18	LH FOGLAMP GARNISH	62257-6UA0A	106.60	
19	RH FOGLAMP GARNISH	62256-6UA0A	106.60	
20	FRT BUMPER	62022-6UA0B	1153.60	
21	LOWER FRT BUMPER	62026-6UA0A	275.80	
22	FRT BUMPER LICENSE PLATE BRACKET	96210-6UA0A	90.40	
23	FRT LICENCE PLATE	FLP		60.00
SUB TOTAL			6008.30	0.00 563.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1201.66	0.00 0.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNG6374D

			DAMAGED PARTS & PRICES		

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
-----			-----	-----	-----
GRAND TOTAL			4806.64	0.00	563.00
			-----	-----	-----
OVERALL TOTAL			5369.64		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNG6374D

TOTAL LABOUR CHARGES 1678.00
TOTAL SPARE PARTS CHARGES 5369.64

GRAND TOTAL 7047.64 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.