

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22010641/UQY3Q2**Date:** 06/01/2023**REFERENCE**

Insured/Claimant: KEEFE CHUA JUN XIANG Policy No: SP2002787392-01
Date of Loss: 20/10/2022 Nature of Claim: OD Claim No: 202222007618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG7416K**
Make & Model: MINI COOPER, 1.6 (A) Engine No: B239I828
Reg. Date: 22/11/2010 (Man. Year: 2010) Chassis No: WMWSV32020TY82387
Colour: White Odometer: 0 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45Z R17 Rear Tyre Size: 205/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,317.20	31,631.60	8,685.60	21.54
Miscellaneous Items	700.00	380.00	320.00	45.71
Labour	5,960.00	3,800.00	2,160.00	36.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	46,977.20	35,811.60	11,165.60	23.77
Approved Total (Overridden) (\$\$)		25,000.00		
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	46,977.20	24,400.00	22,577.20	48.06
+ GST 7.00/7.00% (\$\$)	3,288.40	1,708.00	1,580.40	48.06
Nett Amount (\$\$)	50,265.60	26,108.00	24,157.60	48.06

INSPECTION

Date of Assignment: 27/10/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 27/10/2022 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	M1-COUPÉ	MINI COOPER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG7416K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN (WCP)	Cracked	650.00 F	*650.00 F
2	1		*FRT WINDSCREEN MOULDING (WCP)	Necessary	60.00 F	*60.00 F
3	1		*FRT BONNET (WCP)	Buckled	1,100.00 F	*1,100.00 F
4	2		*FRT BONNET HINGES (WCP)	Repair	190.00 F	*- F
5	1		*FRT BONNET LOCK (WCP)	Twisted	100.00 F	*100.00 F
6	1		*FRT BONNET SCOOP (WCP)	Cracked	230.00 F	*230.00 F
7	1		*FRT BONNET MOULDING (WCP)	Cracked	135.00 F	*135.00 F
8	1		*FRT BONNET CENTRE LOGO (WCP)	Necessary	95.00 F	*95.00 F
9	1		*FRT GRILLE (WCP)	Cracked	145.00 F	*145.00 F
10	1		*FRT BONNET TRIM (WCP)	Not fitted	220.00 F	*- F
11	1		*FRT BUMPER (WCP)	Distorted	780.00 F	*780.00 F
12	1		*FRT BUMPER RETAINER RH (WCP)	Cracked	50.00 F	*50.00 F
13	10		*FRT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
14	1		*FRT BUMPER TOW COVER (WCP)	Torn	50.00 F	*50.00 F
15	1		*FRT BUMPER LOWER GRILLE (WCP)	Torn	125.00 F	*125.00 F
16	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	450.00 F	*450.00 F
17	1		*RH FOG LAMP (WCP)	Broken	195.00 F	*195.00 F
18	1		*RH FOG LAMP GARNISH (WCP)	Broken	105.00 F	*105.00 F
19	1		*RH HEADLAMP (WCP)	Broken	800.00 F	*800.00 F
20	1		*RH HEADLAMP RIM (WCP)	Broken	95.00 F	*95.00 F
21	1		*RH HEADLAMP NPPZLE (WCP)	Broken	105.00 F	*105.00 F
22	1		*RH HEADLAMP NOOZLE COVER (WCP)	Torn	45.00 F	*45.00 F
23	1		*HEADLAMP NOOZLE HOSE (WCP)	Torn	80.00 F	*80.00 F
24	1		*HEADLAMP SUPPORT PANEL (WCP)	Cracked	650.00 F	*650.00 F
25	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	620.00 F	*620.00 F
26	1		*RADIATOR (WCP)	Bent / Punctured	600.00 F	*600.00 F
27	1		*RADIATOR LOWER HOSE (WCP)	Cut	145.00 F	*145.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*AIRCON LIQUID PIPE (WCP)	Bent	160.00 F	*160.00 F
29	1		*AIRCON DISCHARGE PIPE (WCP)	Bent	185.00 F	*185.00 F
30	1		*FRT RH FENDER (WCP)	Distorted	980.00 F	*980.00 F
31	1		*FRT RH FENDER INNER COWLING (WCP)	Torn	230.00 F	*230.00 F
32	10		*INNER COWLING CLIPS (WCP)	Necessary	30.00 F	*30.00 F
33	1		*FRT RH FENDER OUTER TRIM (WCP)	Distorted	250.00 F	*250.00 F
34	1		*FRT RH FENDER SIGNAL LAMP (WCP)	Not Necessary	95.00 F	*- F
35	1		*FRT RH FENDER PROTECTOR (WCP)	Not Necessary	185.00 F	*- F
36	2		*FRT BUMPER PROTECTOR (WCP)	Not Necessary	320.00 F	*- F
37	1		*FRT RH SHOCK ABSORBER (WCP)	Not Necessary	250.00 F	*- F
38	1		*FRT RH LOWER ARM (WCP)	Buckled	280.00 F	*280.00 F
39	1		*FRT RH KNUCKLE ARM (WCP)	Bent	380.00 F	*380.00 F
40	1		*FRT RH KNUCKLE BEARING (WCP)	Necessary	260.00 F	*260.00 F
41	1		*FRT RH DRIVE SHAFT (WCP)	Broken	1,650.00 F	*1,650.00 F
42	1		*STEERING RACK ASSY (WCP)	Bent / Jammed	3,950.00 F	*3,950.00 F
43	1		*STEERING CROSSMEMBER (WCP)	Bent / Twisted	1,250.00 F	*1,250.00 F
44	1		*FRT RH ABS SENSOR (WCP)	Not Necessary	175.00 F	*- F
45	1		*ANTI ROLL BAR LINK RH (WCP)	Bent	90.00 F	*90.00 F
46	1		*FRT ANTI ROLL BAR (WCP)	Not Necessary	250.00 F	*- F
47	1		*FRT RH WHEEL HOUSING PANEL (WCP)	Repair	980.00 F	*- F
48	1		*FRT RH DOOR PILLAR (WCP)	Badly Dented	2,200.00 F	*2,200.00 F
49	1		*STEERING AIRBAG (WCP)	Activated	950.00 F	*950.00 F
50	1		*AIRBAG CONTROL UNIT (WCP)	Activated	950.00 F	*950.00 F
51	1		*CLOCK SENSOR (WCP)	Activated	800.00 F	*800.00 F
52	1		*FRT RH AIRBAG SENSOR (WCP)	Activated	195.00 F	*195.00 F
53	2		*FRT SAFETY BELT	Activated	760.00 F	*760.00 F
54	1		*DASHBOARD (WCP)	Buckled	980.00 F	*980.00 F
55	1		*FRT RH FENDER TOP MOULDING (WCP)	Not Necessary	190.00 F	*- F
56	1		*RH SIDE SKIRT (12 PCS) (WCP)	Distorted (1 PCS ONLY)	3,000.00 F	*250.00 F
57	12		*RH SIDE SKIRT CLIPS (WCP)	Necessary	3.00 F	*36.00 F
58	1		*RH SIDE SKIRTS PROTECTOR (WCP)	Distorted	125.00 F	*125.00 F
59	1		*FAN BELT (WCP)	Cut	65.00 F	*65.00 F
60	1		*ENGINE MOUNTING (WCP)	Serviceable	550.00 F	*- F
61	1		*AIRCON COMPRESSOR (WCP)	Not Necessary	1,250.00 F	*- F
62	2		*ENGINE UNDER COVER (WCP)	Not fitted	390.00 F	*- F
63	8		*UNDER COVER CLIPS (WCP)	Not Necessary	24.00 F	*- F

Report was unsubmitted during this print-out.

1/6/23, 1:42 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*WIPPER GARNISH (WCP)	Not Necessary	110.00 F	*- F
65	1		*FRT PASSENGER AIRBAG (WCP)	Activated	1,300.00 F	*1,300.00 F
Supplementary #1						
66	1		*FAN BELT TENSIONER (WCP)	Twisted	65.00 F	*65.00 F
67	1		*INTERCOOLER (WCP)	Twisted / Cracked	950.00 F	*950.00 F
68	1		*RADITOR FAN ASSY (WCP)	Cracked / Jammed	750.00 F	*750.00 F
69	2		*FRT SEAT BELT BUCKLE (WCP)	Activated	760.00 F	*760.00 F
70	1		*INTERCOOLER HOSE (WCP)	Cracked	495.00 F	*495.00 F
F=Franchise part.						
					Sub Total (\$\$)	36,652.00 28,756.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	3,665.20 2,875.60
					Total Parts (\$\$)	40,317.20 31,631.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ERP BRACKET (NECESSARY)	25.00	15.00
2	1	FRT RH SPORT RIM (CRACKED)	300.00	300.00
3	1	FRT RH TYRE (SERVICEABLE)	250.00	0.00
4	1	FRT WINDSCREEN GUM (NECESSARY)	60.00	40.00
5	1	NUMBER PLATE (NOT NECESSARY)	40.00	0.00
6	1	RADIATOR COOLANT (NECESSARY)	25.00	25.00
Sub Total (\$\$)			700.00	380.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX FRT UNDER CARRIAGE (WITH RACK AND CROSSMEMBER)	New	350.00	350.00
4	4 WHEEL ALIGNMENT	New	80.00	70.00
5	REMOVE & REFIX AIRCON COMPRESSOR & 1 SET ENGINE MOUNTING	New	250.00	0.00
6	REMOVE & REFIX FRT WINDSCREEN	New	120.00	120.00
7	REMOVE & REFIX 2 PCS SAFETY BELT AND AIRBAG SYSTEM	New	350.00	200.00
8	REMOVE & REFIX DASHBOARD	New	280.00	250.00
9	REPROGRAMME AIRBAG SYSTEM	New	300.00	200.00
10	REPAIR WIRE HARNESS	New	120.00	80.00
11	REMOVE & REFIX CUSHION AND SEATS	New	180.00	0.00
12	LABOUR CHARGE	New	2,200.00	1,400.00
13	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			5,960.00	3,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >