

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010642/KQY3Q2**Date:** 23/12/2022**REFERENCE**

Insured/Claimant: NEO BENG SENG Policy No: DMPCSNW00239062100

Date of Loss: 22/10/2022 Nature of Claim: OD Claim No: SNM22D207595/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ7045G**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Reg. Date: 29/11/2019 (Man. Year: 2019)

Colour: Metallic Grey

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$81,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G4FGKU010914

Chassis No: KMHD841CMLU027470

Odometer: 28283 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Front Left Side: Kumho 7 mm

Front Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 205/55 R16

Rear Left Side: Kumho 7 mm

Rear Right Side: Kumho 7 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,570.40	4,384.60	1,185.80	21.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,370.00	1,120.00	44.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,060.40	5,754.60	2,305.80	28.61
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	7,560.40	5,254.60	2,305.80	30.50
+ GST 7.00/7.00% (S\$)	529.23	367.82	161.41	30.50
Nett Amount (S\$)	8,089.63	5,622.42	2,467.21	30.50

INSPECTION

Date of Assignment: 27/10/2022

Date Inspected: 28/10/2022 Inspected At:

160 Sin Ming Drive #07-19 Sin Ming Autocity
Repairer: Chin Nam Hup Kee Motor Works Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMQ7045G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	550.00 F	*550.00 F
2	1		*BONNET INSULATION (WCP)	Serviceable	90.00 F	*- F
3	14		*BONNET INSULATION CLIP (WCP)	Necessary	25.20 F	*25.20 F
4	2		*BONNET HINGES (WCP)	Repair	46.00 F	*- F
5	1		*BONNET LOCK (WCP)	Repair	60.00 F	*- F
6	1		*FRONT GRILLE (WCP)	Cracked	370.00 F	*370.00 F
7	1		*FRONT NO PLATE (WCP)	Dented	35.00 F	*35.00 F
8	1		*FRONT NO PLATE GARNISH (WCP)	Dented	13.00 F	*13.00 F
9	1		*FRONT BUMPER TOP GARNISH (WCP)	Not Necessary	40.00 F	*- F
10	1		*FRONT BUMPER (WCP)	Buckled	600.00 F	*600.00 F
11	1		*FRONT BUMPER TOW COVER (WCP)	Missing	7.00 F	*7.00 F
12	2		*FRONT BUMPER RETAINER (WCP)	Distorted	30.00 F	*30.00 F
13	2		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	160.00 F	*160.00 F
14	1		*FRONT BUMPER SPONGE (WCP)	Cracked	58.00 F	*58.00 F
15	1		*LH FOG LAMP (WCP)	Serviceable	80.00 F	*- F
16	1		*LH FOG LAMP GARNISH (WCP)	Dented	20.00 F	*20.00 F
17	1		*RH FOG LAMP (WCP)	Serviceable	80.00 F	*- F
18	1		*RH FOG LAMP GARNISH (WCP)	Serviceable	20.00 F	*- F
19	1		*LH HEADLAMP (WCP)	Cut	620.00 F	*620.00 F
20	1		*RH HEADLAMP (WCP)	Cracked	620.00 F	*620.00 F
21	1		*LH HEADLAMP LOWER BRACKET (WCP)	Serviceable	25.00 F	*- F
22	1		*RH HEADLAMP LOWER BRACKET (WCP)	Serviceable	25.00 F	*- F
23	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Serviceable	40.00 F	*- F
24	6		*FRONT SUPPORT PANEL TOP GARNISH CLIP (WCP)	Necessary	10.80 F	*10.80 F
25	1		*FRONT SUPPORT PANEL (WCP)	Cracked	260.00 F	*260.00 F
26	1		*RADIATOR (WCP)	Housing Cracked	145.00 F	*145.00 F
27	1		*RADIATOR COOLANT (WCP)	Necessary	16.00 F	*16.00 F
28	1		*AC CONDENSER (WCP)	Punctured	160.00 F	*160.00 F
29	1		*RADIATOR FAN ASSY (WCP)	Serviceable	150.00 F	*- F
30	1		*RADIATOR AIR DUCT LH (WCP)	Cracked	25.00 F	*25.00 F
31	1		*RADIATOR AIR DUCT RH (WCP)	Distorted	25.00 F	*25.00 F
32	1		*HEADLAMP LOWER BRACKET LH (WCP)	Cracked	18.00 F	*18.00 F
33	1		*HEADLAMP LOWER BRACKET RH (WCP)	Cracked	18.00 F	*18.00 F
34	1		*FOG LAMP LOWER GARNISH LH (WCP)	Distorted	58.00 F	*58.00 F
35	1		*FOG LAMP LOWER GARNISH RH (WCP)	Distorted	58.00 F	*58.00 F
36	1		*FRONT BUMPER SIDE SUPPORT RH (WCP)	Mtg Cracked	20.00 F	*20.00 F
37	1		*FRONT GRILLE SUPPORT LH (WCP)	Cracked	8.00 F	*8.00 F
38	1		*FRONT GRILLE SUPPORT RH (WCP)	Cracked	8.00 F	*8.00 F
39	1		*FRONT SUPPORT TOP GARNISH (WCP)	Cracked	48.00 F	*48.00 F

F=Franchise part.

Sub Total (\$\$)	4,642.00	3,986.00
+ Margin on L,N Items 20.00/10.00% (\$\$)	928.40	398.60
Total Parts (\$\$)	5,570.40	4,384.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	60.00	50.00
2	PANEL BEATING LABOUR	New	1,000.00	600.00
3	PUTTY AND SPRAY PAINT	New	1,000.00	600.00
4	CHECK ELECTRICAL LIGHTINGS	New	120.00	20.00
5	REPLACE AC CONDENSER AND RECHARGE AC GAS	New	150.00	100.00
6	RUSTPROOF WELDED AND AFFECTED SECTION	New	80.00	0.00
7	COMPUTERISED WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (S\$)			2,490.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >