



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 1462E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER (CONSISTENT)	CUT	135.00	105.00
2	FORK TUNE ASSY -L/R (CONSISTENT)	NOT NECESSARY	980.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	285.00	-
1	FRONT SPORT RIM (CONSISTENT)	WARPED	420.00	420.00
1	FRONT RIM SHAFT (CONSISTENT)	SERVICEABLE	145.00	-
1	FRONT RIM BEARING (CONSISTENT)	NECESSARY	105.00	50.00
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	235.00	-
1	WINDSHIELD (CONSISTENT)	CRACKED	385.00	220.00
1	HANDLE -BAR (CONSISTENT)	BENT	385.00	250.00
1	HANDLE -BAR END (N/S) (CONSISTENT)	TWISTED	155.00	40.00
1	HAND-GRIP (N/S) (CONSISTENT)	TORN	95.00	75.00
1	SIDE MIRROR (N/S) (CONSISTENT)	BROKEN	180.00	80.00
1	CLUTCH LEVER (N/S) (CONSISTENT)	CRACKED	190.00	125.00
1	FRONT SIGNAL (N/S) (CONSISTENT)	BROKEN	140.00	60.00
1	HEADLAMP COVER (CONSISTENT)	CUT	185.00	185.00
1	SIDE COWLING -MATT (CONSISTENT)	CUT	225.00	145.00
1	FRONT SIDE LOWER COVER (CONSISTENT)	CUT	175.00	90.00
1	FUEL TANK SIDE COVER -L/H (CONSISTENT)	CUT	255.00	255.00
2	FRONT FOOTREST (CONSISTENT)	N/S BROKEN	180.00	60.00
2	FRONT FOOTREST BRACKETS (CONSISTENT)	N/S CRACKED	450.00	145.00
1	GEAR PEDAL (CONSISTENT)	BENT	135.00	110.00
2	REAR FOOTRESTS (CONSISTENT)	N/S CUT	180.00	60.00
2	REAR FOOTREST BRACKETS (CONSISTENT)	N/S CUT	480.00	180.00
1	REAR SIDE COVER -L/H (CONSISTENT)	CRACKED	285.00	285.00
1	SIDE STAND (CONSISTENT)	TO REPAIR SEE LABOUR	125.00	-
1	SET REAR SIGNALS (CONSISTENT)	CUT	140.00	60.00
	LESS 10% DISCOUNT		-665.00	-300.00
			5,985.00	2,700.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	NUMBER PLATE (SN) (CONSISTENT)	FRT NECESSARY	38.00	10.00

Report Ref No. CC4/ASM22010643/Upa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	95.00	-
1	E.R.P IU (SN) (CONSISTENT)	CUT	180.00	165.00
1	REAR BOX (SN) (CONSISTENT)	CUT	480.00	350.00
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET MT-15 STICKER (SN) (CONSISTENT)	NECESSARY	150.00	80.00
			1,209.00	605.00
	<b>LABOUR</b>			
	TO REMOVE ,REFIT AND ALIGN BODY FRAME.	NOT NECESSARY	380.00	-
	TO CHECK WIRINGAND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF SIDE STAND.		400.00	300.00
			860.00	300.00
<b>GRAND TOTAL</b>			<b>8,054.00</b>	<b>3,605.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,800.00</b>

Report Ref No. CC4/ASM22010643/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.