

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 7269P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT / CRACKED	7,800.00	4,800.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	815.00	-
1	SET REAR BUMPER CLIPS & RIVET	NECESSARY	60.00	60.00
1	REAR BUMPER SIDE HOLDER O/S	NOT NECESSARY	166.20	-
1	REAR TAILLAMP O/S	NOT NECESSARY	1,028.00	-
1	REAR FENDER O/S	BADLY DENTED / DISTORTED	5,228.20	3,926.73
1	REAR FENDER OUTER PROTECTOR O/S	TORN	645.10	520.00
1	REAR FENDER UNDER TRIM O/S	TORN	611.10	385.00
1	SET REAR FENDER UNDER TRIM CLIPS O/S	NECESSARY	50.00	50.00
1	REAR FENDER INNER PANEL O/S	TO REPAIR SEE LABOUR	3,882.00	-
1	REAR SHOCK ABSORBER O/S	SERVICEABLE	888.90	-
1	REAR KNUCKLE ARM O/S	BENT	1,888.20	1,465.00
1	REAR WHEEL HUB BEARING O/S	DAMAGED	850.00	650.00
1	REAR TORSION ARM O/S	BENT	689.20	366.00
1	REAR TRUST ARM O/S	BENT	455.20	305.00
1	REAR LINK ARM O/S	NOT NECESSARY	355.00	-
1	REAR LOWER ARM O/S	BENT	918.90	615.00
1	REAR SPORT RIM O/S	WARPED	2,200.00	1,200.00
1	REAR TYRE O/S	SERVICEABLE	300.00	-
1	FRONT DOOR O/S	BADLY DENTED	6,899.20	5,800.00
1	FRONT DOOR INNER LOCK O/S	DAMAGED	969.20	390.00
1	FRONT DOOR INNER RUBBER O/S	TORN	399.20	280.00
1	FRONT DOOR INNER TRIM BOARD O/S	DEFORMED / TORN	1,450.20	1,150.00
1	SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	NECESSARY	60.00	60.00
1	FRONT DOOR OUTER PROTECTOR	TORN	299.80	299.80
1	FRONT DOOR OUTER TOP MOULDING O/S	BENT	388.20	118.00
1	FRONT DOOR GLASS REGULATOR & MOTOR O/S	NOT NECESSARY	1,241.50	-
1	FRONT DOOR MIRROR OUTER COVER O/S	CRACKED	388.00	105.00
1	FRONT DOOR MIRROR ASSY O/S	CRACKED	1,500.80	980.00

Report Ref No. CS/SMO22010644/Uvy3m4



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT DOOR SPEAKER O/S	CRACKED	650.00	285.00
1	FRONT DOOR INNER HANDLE BRACKET O/S	NOT NECESSARY	241.10	-
1	FRONT DOOR OUTER HANDLE O/S	GRAZED	366.00	290.00
1	FRONT DOOR OUTER HANDLE END O/S	GRAZED	68.00	68.00
1	ROCKER PANEL GARNISH O/S	TORN	820.20	820.20
1	SET ROCKER PANEL GARNISH CLIPS O/S	NOT NECESSARY	50.00	-
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	1,299.00	-
1	ROCKER PANEL INNER STEP GARNISH O/S	TORN	455.00	245.00
	LESS 10% DISCOUNT		-	-2,523.37
			46,376.40	22,710.36
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	280.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.		300.00	150.00
	TO DISMANTLE & REFIX FUEL TANK.		100.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		150.00	100.00
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM.		180.00	60.00
	TO DIAGNOSE AND CALIBRATE RESET CONVERTIBLE SOFT COVER.		500.00	300.00
	TO SPRAY RUST PROOFING.		180.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL O/S AND ROCKER PANEL O/S.		2,000.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,100.00
			6,770.00	2,930.00
	GRAND TOTAL		53,146.40	25,640.36



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		20,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO22010644/Uvy3m4

CHUA KANG SENG
Licensed Appraiser