



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 1062K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	199.50	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,550.20	-
1	TAILGATE 'PRIUS' EMBLEM	NECESSARY	105.10	105.10
1	TAILGATE 'HYBRID' EMBLEM	NECESSARY	90.00	90.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	388.90	-
1	TAILGATE INNER LOCK	NOT NECESSARY	650.20	-
1	REAR BUMPER	DISTORTED	1,250.00	825.10
2	REAR BUMPER SIDE RETAINERS @\$85.00	NECESSARY	170.00	170.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS @\$98.00	N/S CRACKED	196.00	98.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	911.20	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	245.20	-
2	TAILLAMPS @\$950.10	SERVICEABLE	1,900.20	-
1	TAILLAMP LOWER BRACKET N/S	CRACKED	65.00	65.00
	LESS 25% DISCOUNT		-	-350.80
			7,771.50	1,052.40
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER BLACK STICKER (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			450.00	200.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX TAILGATE MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		150.00	60.00

Report Ref No. CS/AGI22010646/Uny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL .		800.00	680.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	700.00
			2,430.00	1,510.00
GRAND TOTAL			10,651.50	2,762.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/AGI22010646/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.