Adjuster Report 12/29/22, 10:13 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22010650/UVY3E2

Date: 29/12/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001983683 **Claimant Vehicle** SNG4058E Insured Vehicle No: **GBH8747K**

No:

Date of Loss: 25/10/2022 Nature of Claim: TP Claim No: 288738

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNG4058E

SUBARU IMPREZA, 1.5 R AWD 5MT ABS Make & Model: Engine No: EL15D643673

AIRBAG (M) 31/12/2009 (Man. Year: 2008) JF1GE3KF39G003983 Reg. Date: Chassis No:

Colour: Grey Odometer: 140610 km

Engine Capacity: 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17 Front Left Side: Rear Left Side: Pirelli 6 mm Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	756.80	691.60	65.20	8.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	820.00	710.00	46.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	2,286.80	1,511.60	775.20	33.90
Approved Total (Overridden) (S	\$\$)	1,200.00		
(S	2,286.80	1,200.00	1,086.80	47.52
+ GST 7.00/7.00% (S	(\$) 160.08	84.00	76.08	47.53
Nett Amount (S	2,446.88	1,284.00	1,162.88	47.53

INSPECTION

Date of Assignment: 28/10/2022

Date Inspected: 27/10/2022 Inspected At: No 1 Kaki Bukit Ave 6, #02-34/36

Precise Auto Service (HQ)

Singapore 417883

Estimated Period of Repair: 3.0 days

MARCUS CHUA Adjuster: Manager: **VERON CHEN** NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2022)

Parts: 143 SUBARU IMPREZA 1.5 R AWD 5MT ABS AIRBAG (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNG4058E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	680.00 FL	*680.00 FL
2	1		*FRONT BUMPER SIDE RETAINER - RH	Cracked	26.00 FL	*26.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	32.00 FL	*32.00 FL
4	1		*FRONT BUMPER BRACKET - RH	Not Necessary	44.00 FL	*-FL
5	1		*HEAD LAMP LOWER BRACKET	Cracked	64.00 FL	*64.00 FL
6	1		*HEAD LAMP STICKER (ACC)	Necessary	80.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	,		
				Sub Total (S\$)	926.00	852.00
			- List Item Discount o	n L Items 20.00/20.00% (S\$)	169.20	160.40
				Total Parts (S\$)	756.80	691.60

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	500.00
3	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT RH FENDER, FRONT SUPPORT PANEL & ALIGNED ALL PARTS	New	650.00	300.00
	Gross Labo	our Cost (S\$)	1,530.00	820.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >