



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 171H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	717.00	617.00
1	REAR BUMPER REINFORCEMENT	DENTED	368.00	273.00
1	REAR BUMPER RETAINER LH	CRACKED	48.00	48.00
1	REAR BUMPER RETAINER RH	CRACKED	48.00	48.00
1	REAR BUMPER BRACKET LH	CRACKED	58.00	58.00
1	REAR BUMPER BRACKET RH	CRACKED	58.00	58.00
1	REAR REFLECTOR WITH COVER LH	NOT NECESSARY	165.00	-
1	REAR REFLECTOR WITH COVER RH	CRACKED	165.00	165.00
1	REAR BUMPER INNER GRILLE LH	NOT NECESSARY	117.00	-
1	REAR BUMPER INNER GRILLE RH	CRACKED	117.00	117.00
1	REAR BUMPER FIN LH	NOT NECESSARY	85.00	-
1	REAR BUMPER FIN RH	NOT NECESSARY	85.00	-
1	BOOTLID LOCK	NOT NECESSARY	185.00	-
1	REAR LOCK SENSOR	NOT NECESSARY	255.00	-
1	ANTHENA SENSOR	MALFUNCTION	290.00	168.00
4	REAR DISTANCE SENSOR	MALFUNCTION (2PCS ONLY)	900.00	290.00
1	SENSOR COVER	NOT NECESSARY	120.00	-
1	BOOTLID WEATHERSTRIP	DEFORMED	85.00	85.00
1	END PANEL	DENTED	514.00	436.00
1	END PANEL TOP GARNISH	DEFORMED	119.00	119.00
1	REAR TAILLAMP LH	NOT NECESSARY	482.00	-
1	REAR TAILLAMP RH	NOT NECESSARY	482.00	-
	LESS 25% DISCOUNT		-1,365.75	-620.50
			4,097.25	1,861.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	30.00
			200.00	60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.		150.00	50.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	30.00
	REMOVE AND STRAIGHTEN REAR EXHAUST.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS.		1,400.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
			3,540.00	1,540.00
	<b>GRAND TOTAL</b>		<b>7,837.25</b>	<b>3,461.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,750.00</b>

Report Ref No. CS3/INC22009014/Gny3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.