



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 8004H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	TO REPAIR SEE LABOUR	1,225.00	-
2	REAR BOOT HINGE	NOT NECESSARY	298.30	-
1	REAR BOOT LOGO	NECESSARY	120.00	120.00
1	REAR BOOT LOCK	BENT	355.00	355.00
1	REAR BOOT "HYBRID"	NECESSARY	85.00	85.00
1	REAR BOOT PANEL WITH "CAMRY"	NOT NECESSARY	319.70	-
2	REAR BOOT LAMP	NOT NECESSARY	640.00	-
1	REAR BOOT RUBBER	TORN	198.85	198.85
1	REAR LAMP LH	CUT	720.00	605.70
1	REAR LAMP RH	CUT	720.00	605.70
1	REAR BUMPER	DENTED	800.00	657.00
2	REAR BUMPER SIDE RETAINER	BROKEN	170.00	170.00
2	REAR BUMPER LOWER SPOILER	NOT NECESSARY	240.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	520.69	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	335.70	-
2	REAR BUMPER SENSOR	NOT NECESSARY	570.00	-
1	SET REAR BUMPER SENSOR SEAL	NECESSARY	24.00	24.00
1	REINFORCEMENT BAR (ADDITIONAL)	BENT	380.00	380.00
1	REAR FLOOR CARPET (ADDITIONAL)	CRUSHED	520.00	520.00
	LESS 25% DISCOUNT		-2,060.56	-930.32
			6,181.68	2,790.93
<u>SPECIAL NETT ITEMS</u>				
1	CAR PLATE NUMBER WITH FRAME (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER & FENDER SHIELD CLIPS (SN)	NECESSARY	35.00	30.00
1	SET REAR INNER FENDER & BOOT INSULATOR CLIPS (SN)	NOT NECESSARY	70.00	-
			155.00	30.00
<u>LABOUR</u>				
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,000.00	600.00

Report Ref No. CS/SMR22010652/Ecy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL.		1,000.00	600.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	30.00
	ANTI RUST TREATMENT.		100.00	30.00
	TO REMOVE / REFIX REAR INNER COMPARTMENT TO FACILITATE REPAIR.		180.00	30.00
	TO REMOVE / REPLACE REVERSE SENSOR.		180.00	30.00
	TO REMOVE / REFIX REAR REVERSE CAMERA.	NOT NECESSARY	180.00	-
	TO REMOVE / REFIX / REPLACE REAR BOOT INNER COMPARTMENT, MECHANISM & ASSY TO NEW BOOT. (NPA)	NOT NECESSARY	-	-
	COMPUTER DIAGNOSTIC.		350.00	50.00
	TO CHECK WATER LEAKING.		150.00	30.00
			3,240.00	1,400.00
GRAND TOTAL			9,576.68	4,220.93
RECOMMENDED COST OF REPAIRS				4,220.93

Report Ref No. CS/SMR22010652/Ecy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.