

51 AUTOMOTIVE PTE LTD

Hub
#01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

O2 AIRCON ENGINEERING PTE LTD
157 JALAN TECK WHYE #03-123
SINGAPORE 680157

Contact : 94461627 88548036

TAX INVOICE

Repair Code : CLM17428

Date in : 25/10/2022

Vehicle Num. : GBK5911G

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P909990430/1KDB047825

10 AXA
Xiao Tony

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>2nd</i>	1	673.10	✓ 673.10
REAR BUMPER LOWER BRACKET <i>Best 2 pieces</i>	4	60.20	120.80 240.80
REAR BUMPER SIDE RETAINER L/R <i>me</i>	2	59.15	✓ 118.30
REAR END PANEL (INNER) <i>Regr</i>	1	1304.20	+ 1,304.20
REAR END PANEL (OUTER) <i>Defect</i>	1	459.90	✓ 459.90
REAR END PANEL INNER TOP PLATE <i>me</i>	1	195.00	+ 195.00
REAR RH TAILLAMP <i>nt</i>	1	475.80	335 ✓ 475.80
REAR RH TAILLAMP LOWER GARNISH <i>me</i>	1	93.20	+ 93.20
REAR RH TAILLAMP LOWER GARNISH SIDE BRACKET <i>me</i>	1	57.10	+ 57.10
REAR SPARE TYRE CARRIAGE <i>Best</i>	1	378.90	✓ 378.90
REAR SPARE TYRE CARRIAGE BRACKET WITH SCREW <i>me</i>	1	230.10	+ 230.10
REAR TAILGATE <i>Defect</i>	1	2492.70	1855 2,492.70
REAR TAILGATE 'LOGO' EMBLEM <i>me</i>	1	72.20	✓ 72.20
REAR TAILGATE HINGES L/R <i>me</i>	2	68.20	+ 136.40
REAR TAILGATE INNER CENTER LOCK CENTRAL ASSY <i>Defect</i>	1	578.10	365 578.10
REAR TAILGATE INNER TRIM BOARD <i>tom</i>	1	570.10	168 570.10
REAR TAILGATE MECHANISM LOCK <i>Defect</i>	1	264.70	✓ 264.70
REAR TAILGATE OUTER HANDLE <i>nt</i>	1	370.10	✓ 370.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

O2 AIRCON ENGINEERING PTE LTD
 157 JALAN TECK WHYE #03-123
 SINGAPORE 680157

Contact : 94461627 88548036

TAX INVOICE

Repair Code : CLM17428

Date in : 25/10/2022

Vehicle Num. : GBK5911G

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P909990430/1KDB047825

REAR TAILGATE THIRD BRAKE LAMP <i>new</i>	1	378.90	+	378.90
REAR TAILGATE WEATHER STRIP <i>lt</i>	1	391.20	✓	391.20
REAR TAILGATE WINDSCREEN <i>shuttered</i>	1	1419.80	1115 ✓	1,419.80
REAR TAILGATE WIPER ARM <i>new</i>	1	171.20	+	171.20
REAR TAILGATE WIPER MOTOR <i>new</i>	1	789.10	+	789.10
Subtotal before discount				11,860.90
Percentage discount 25%				2,965.23
Sub-total 1				8,895.68
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00
REAR RH TAILLAMP CLIP - SET <i>new</i>	1	25.00	60	25.00
REAR RH TAILLAMP LOWER GARNISH CLIP - SET <i>new</i>	1	15.00	4	15.00
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00	15	25.00
REAR TAILGATE '8PAX' STICKER <i>new</i>	1	25.00	15	25.00
REAR TAILGATE 'COMPANY' STICKER <i>new</i>	1	800.00	380	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	20	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	✓	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	30	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET <i>new</i>	1	25.00	10	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

O2 AIRCON ENGINEERING PTE LTD
157 JALAN TECK WHYE #03-123
SINGAPORE 680157

TAX INVOICE

Repair Code : CLM17428

Date in : 25/10/2022

Vehicle Num. : GBK5911G

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P909990430/1KDB047825

Contact : 94461627 88548036

REAR TAILGATE WINDSCREEN SEAL

REAR TAILGATE WINDSCREEN SEALANT

1

80.00

1

80.00

Subtotal before discount

Percentage discount 0%

Sub-total 2

Parts-total

1,280.00

0.00

1,280.00

10,175.68

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

2,530.00

12,705.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
2/s 26/10/22
06 hrs

Total: 7500.12
L/s: GK

GK