

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HSBC LIFE (SING	APORE) PTE LTD	Re	ef:	CC4/ASM22010662/Apa3q2	
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Da	ate:	04/05/2023	
	ATTN:YVONNE		Co	ode:	HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBN 9675X	Veh. Inspected		GBK 5911G	
	Policy No.	P2471433	Coverage (\$)		0.00	
	Claim No.	S2M04DEW	Excess (\$)		0.00	
	Assign From		Assign Date		26/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTFHT02P909990430	Colour		GREY	
	Odometer	81320 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15C	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/10/2022	Inspection Date		26/10/2022	
	Survey held at	N-51 AUTOMOTIVE PL				
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				