



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 7276M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR LEFT SLIDING DOOR ASSY	DENTED / BENT	1,812.00	1,602.00
1	REAR LEFT SLIDING DOOR LOCK	NOT NECESSARY	289.00	-
1	REAR LEFT SLIDING DOOR RAILING	NOT NECESSARY	276.00	-
1	REAR LEFT FENDER PANEL	TO REPAIR SEE LABOUR	4,800.00	-
	LESS 25% DISCOUNT		-1,794.25	-400.50
			5,382.75	1,201.50
SPECIAL NETT ITEMS				
1	REAR LEFT FENDER PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
LABOUR				
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN ACCIDENT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR LEFT FENDER PANEL.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINTING ACCIDENT PORTION.		1,000.00	500.00
	TO CHECK REAR LIGHTING AND WIRING.	NOT NECESSARY	50.00	-
	TO REMOVE AND INSTALL REAR LEFT SLIDING DOOR LOCK.		80.00	50.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			2,230.00	1,050.00
GRAND TOTAL			7,692.75	2,251.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,800.00

Report Ref No. CS/INC22010666/Uny3m4

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.