

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 706C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	BUCKLED / MTG CRACKED	1,450.00	1,012.00
1	REAR BUMPER LOWER GARNISH	DENTED / CUT	580.00	573.10
1	SET REAR BUMPER CLIPS	NECESSARY	80.00	80.00
1	REAR BUMPER CENTRE RETAINER	SERVICEABLE	130.00	-
2	REAR BUMPER SIDE RETAINERS	SERVICEABLE	260.00	-
2	REAR BUMPER REFLECTORS	SERVICEABLE	360.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	680.00	-
2	REAR NUMBER PLATE LAMPS	SERVICEABLE	120.00	-
1	REAR BOOT ASSY	TO REPAIR SEE LABOUR	3,000.00	-
1	REAR BOOT LOGO	NOT NECESSARY	180.00	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	269.00	-
1	REAR BOOT EMBLEM " GOLF "	NECESSARY	150.00	90.80
1	REAR BOOT EMBLEM " TSI "	NECESSARY	120.00	108.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	750.00	-
	LESS 10% DISCOUNT		-812.90	-186.39
			7,316.10	1,677.51
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SERVICEABLE	200.00	_
1	REAR NUMBER PLATE (SN)	SERVICEABLE	100.00	-
	, ,		300.00	-
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR		800.00	300.00
	BUMPER REINFORCEMENT, REAR BOOT ASSY, REAR BOOT LOCK AND REAR END PANEL.			
	PAINTING.		800.00	400.00

Report Ref No. CS/AGI22010668/Kny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,800.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	ANTI RUST.	NOT NECESSARY	100.00	-
			1,700.00	700.00
	GRAND TOTAL		9,316.10	2,377.51

Report Ref No. CS/AGI22010668/Kny3m4

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser