12/30/22, 11:12 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22010673/UPA3Q2

Date: 30/12/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:

Claimant Vehicle SJB4015C Insured Vehicle No: PC5461P

No:

Date of Loss: 10/10/2022 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB4015C

 Make & Model:
 HONDA CIVIC, 1.6 (A)
 Engine No:
 R16A13001959

 Reg. Date:
 11/01/2008 (Man. Year: 2007)
 Chassis No:
 JHMFD46208S200587

Colour: Silver Odometer: 157709 km

Engine Capacity: 1595 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|--------------------|------------|------------|--------|
| Parts | 1,460.88 | 0.00 | 1,460.88 | 100.00 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 700.00 | 400.00 | 300.00 | 42.86 |
| Paintwork Labour | 700.00 | 600.00 | 100.00 | 14.29 |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 2,871.88 | 1,011.00 | 1,860.88 | 64.80 |
| Approved Total (Overridden) (S\$) | | 1,000.00 | | |
| (S\$) | 2,871.88 | 1,000.00 | 1,871.88 | 65.18 |
| + GST 7.00/7.00% (S\$) | 201.03 | 70.00 | 131.03 | 65.18 |
| Nett Amount (S\$) | 3,072.91 | 1,070.00 | 2,002.91 | 65.18 |
| - Global Su | m Settlement (S\$) | 0.00 | | |

INSPECTION

Date of Assignment: 21/10/2022 Present Location: Tan Lim Motor Pte Ltd (Defu)

Tan Lim Motor Pte Ltd (Defu)

Date Inspected: 28/10/2022 Inspected At: 1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2022)

Parts: 143 HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJB4015C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------------|-----------------------|-------------------------------|------------|--------|
| 1 | 1 | | *o/s rear door | Repair | 747.80 FL | *- FL |
| 2 | 1 | | *o/s rear door handle | Repair | 182.10 FL | *- FL |
| 3 | 1 | | *o/s rear fender | Repair | 896.20 FL | *- FL |
| F=Fra | anchise | part. L=ListItemDi | sc. | , | | |
| | | | | Sub Total (S\$) | 1,826.10 | 0.00 |
| | | | - List Item Discount | on L Items 20.00/20.00% (S\$) | 365.22 | 0.00 |
| | | | | Total Parts (S\$) | 1,460.88 | 0.00 |
| | | | | | | |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | | Repairer's | Amount |
|------|--------|----------------------|-----------------|------------|--------|
| Misc | cellan | neous Items | | | , |
| 1 | 1 | OD/TP Case (Insurer) | | 11.00 | 11.00 |
| | | | Sub Total (S\$) | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------|---|------------|------------|----------|
| <u>Pair</u> | ntwork Labour | | | |
| 1 | Putty and spray painting of the affected portion. | New | 700.00 | 600.00 |
| <u>Lab</u> | our Items | | | |
| 2 | To transfer of o/s rear door fittings and perform water seepage test. | New | 80.00 | 0.00 |
| 3 | To rust proofing for the accident affected portion. | New | 120.00 | 0.00 |
| 4 | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | New | 500.00 | 400.00 |
| | Gross Labour | Cost (S\$) | 1,400.00 | 1,000.00 |

Report was unsubmitted during this print-out. < END OF ESTIMATES >