

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22010676/ANCE2**Date:** 01/03/2023**REFERENCE**

Insured/Claimant:	LOH CHEE WAI DESMOND	Policy No:	2100511001-05	
Date of Loss:	20/10/2022	Nature of Claim:	OD	Claim No: 7483823413SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SCZ8781D</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX007463
Reg. Date:	20/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZFY1H2030930
Colour:	Blue	Odometer:	51399 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,394.00	13,171.84	9,222.16	41.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,632.00	4,602.00	3,030.00	39.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,026.00</b>	<b>17,773.84</b>	<b>12,252.16</b>	<b>40.81</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>29,526.00</b>	<b>17,273.84</b>	<b>12,252.16</b>	<b>41.50</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>2,362.08</b>	<b>1,381.91</b>	<b>980.17</b>	<b>41.50</b>
<b>Nett Amount (S\$)</b>	<b>31,888.08</b>	<b>18,655.75</b>	<b>13,232.33</b>	<b>41.50</b>

**INSPECTION**

Date of Assignment:	28/10/2022		
Date Inspected:	26/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Distorted	1,789.00 FS	*1,160.80 FS
2	1		*FRONT BUMPER SPOILER	Deformed	850.00 FS	*679.60 FS
3	1		*RADIATOR GRILLE	Not Necessary	3,910.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Torn	126.00 FS	*100.40 FS
5	1		*FRONT BUMPER SECURING STRIP - LH	Necessary	42.00 FS	*33.36 FS
6	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	580.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	651.00 FS	*520.80 FS
8	1		*FRONT BUMPER END CAP - LH	Not Necessary	103.00 FS	*- FS
9	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
10	10		*FRONT PARKING AID SEAL RING	Not Necessary	25.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	43.00 FS	*34.24 FS
12	1		*FRONT FENDER - LH	Dented	1,462.00 FS	*1,169.60 FS
13	1		*FRONT FENDER BRACE - LH	Bent	250.00 FS	*200.00 FS
14	1		*FRONT WHEEL SPOILER	Torn	181.00 FS	*144.40 FS
15	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	303.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
17	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,418.00 FS	*1,134.40 FS
18	1		*HEADLIGHT - LH	Cracked	8,708.00 FS	*6,966.40 FS
19	1		*LIFT CYLINDER - LH	Cracked	153.00 FS	*122.40 FS
20	1		*HEADLIGHT MOUNTING - LH	Cracked	132.00 FS	*105.20 FS
21	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
22	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
23	1		*FRONT BUMPER CLOSING ELEMENT-LOWER (Supplementary)	Torn	246.00 FS	*196.40 FS
24	1		*FRADIATOR STRIKER PLATE (Supplementary)	Cracked	271.00 FS	*216.80 FS
25	1		*FOAM FILLER PIECE (Supplementary)	Cracked	198.00 FS	*158.40 FS
26	1		*FRONT FENDER TOP COVER-LH OUTER (Supplementary)	Deformed	35.00 FS	*27.52 FS
27	1		*FRONT FENDER TOP COVER-LH FRONT (Supplementary)	Deformed	44.00 FS	*35.12 FS
28	1		*HORN-LH (Supplementary)	Cracked	208.00 FS	*166.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**    **22,394.00**    **13,171.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM, AND LHS WING MIRROR ASSY	New	280.00	280.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS POWER MODULE AND CONTROL UNIT	New	480.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER, LOWER SPOILER, LHS FRONT FENDER, LHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	New	3,800.00	2,400.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>7,632.00</b>	<b>4,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >