

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010677/ACE2**Date:** 05/06/2023**REFERENCE**

Insured/Claimant:	YAN JIE	Policy No:	2100490068		
Date of Loss:	17/10/2022	Nature of Claim:	OD	Claim No:	5238825334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9764K		Engine No:	CYR019949
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)		Chassis No:	WAUZZZ4M0HD008373
Reg. Date:	24/11/2016 (Man. Year: 2016)		Odometer:	18105 km
Colour:	Silver			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$145,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,640.00	16,236.24	6,403.76	28.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,972.00	4,192.00	4,780.00	53.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,612.00	20,428.24	11,183.76	35.38
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	30,612.00	19,428.24	11,183.76	36.53
+ GST 8.00/8.00% (S\$)	2,448.96	1,554.26	894.70	36.53
Nett Amount (S\$)	33,060.96	20,982.50	12,078.46	36.53

INSPECTION

Date of Assignment:	28/10/2022		
Date Inspected:	26/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	5,466.00 FS	*4,372.80 FS
2	1		*FRONT OUTER DOOR SEAL	Necessary	282.00 FS	*225.20 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Necessary	74.00 FS	*58.96 FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH - LH	Not Necessary	137.00 FS	*- FS
7	1		*FRONT DOOR COVER - LH	Necessary	734.00 FS	*586.80 FS
8	1		*FRONT EXTERIOR WING MIRROR MOUNTING - LH	Cut	1,664.00 FS	*1,331.20 FS
9	1		*FRONT WING MIRROR CAP - LH	Not Necessary	221.00 FS	*- FS
10	1		*FRONT WING MIRROR GLASS - LH	Chipped	1,737.00 FS	*1,389.60 FS
11	1		*FRONT QUARTER WINDOW - LH	Cut	291.00 FS	*232.40 FS
12	1		*FRONT WINDOW GUIDE - LH	Not Necessary	560.00 FS	*- FS
13	1		*REAR DOOR - LH	Dented	5,708.00 FS	*4,566.40 FS
14	1		*REAR OUTER DOOR SEAL - LH	Necessary	278.00 FS	*222.40 FS
15	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
17	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
18	1		*REAR DOOR CATCH - LH	Not Necessary	137.00 FS	*- FS
19	1		*REAR OUTER DOOR SEAL - LH	Necessary	213.00 FS	*170.40 FS
20	1		*REAR SILL PANEL SEAL - LH	Not Necessary	282.00 FS	*- FS
21	1		*REAR DOOR COVER - LH	Necessary	673.00 FS	*538.40 FS
22	1		*REAR WHEEL COVER - LH	Cut	207.00 FS	*165.20 FS
23	1		*REAR WHEEL COVER - LH	Not Necessary	397.00 FS	*- FS
24	1		*REAR ALUMINIUM RIM	Cut	2,266.00 FS	*1,812.80 FS
25	1		*REAR ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
26	1		*SUNDRIES	Necessary	500.00 FS	*41.12 FS
27	1		*REAR DOOR WINDOW GUIDE - LH (Supplementary)	Necessary	560.00 FS	*475.60 FS
28	1		*DOUBLE-SIDED ADHESIVE TAPE (Supplementary)	Necessary	55.00 FS	*44.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **22,640.00** **16,236.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	900.00	720.00
2	TO INSTALL SOLAR FILM FOR FRONT 1/4 GLASS	New	400.00	0.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,200.00
4	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, 2 DOOR COVERS, DOOR HANDLE, LHS REAR DOOR WHEEL ARCH TRIM AND LHS REAR FENDER WHEEL ARCH TRIM	New	4,500.00	1,800.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,972.00	4,192.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >