

✓SAS-KIV → see attached.

REPAIR ESTIMATEDATE: 25.10.2022✓Police report
(attached)INSURANCE: INCOME CP/PMODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHC8600EMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reinforcement	1		\$ 394.80
	SUB TOTAL			\$ 1,482.45
	LESS 20%			\$ 296.49
	DISCOUNTED TOTAL			\$ 1,185.95
	Reverse Sensors	1		\$ 180.00
	LESS 10%			\$ 18.00
	S/NETT TOTAL	1		\$ 162.00
	Rear Bumper Mat	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 1,397.96
	Labour Charge			\$ 400.00
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 120.00
	Remove/Refix Reverse Sensor			
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 2,217.96

X R
✓DEF
? X SVC
X SVC
? X SVC

X SVC

NETT ✓NEC

350
250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK

25/10/2022 1740 HRS

PIP

2 DAYS

CHECK ITEM PHOTOS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: