



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3416D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	TO REPAIR SEE LABOUR	481.10	-
10	FRT BUMPER CLIPS	SERVICEABLE	22.00	-
1	FRT BUMPER CENTRE MOULDING	SERVICEABLE	368.50	-
1	FRT BUMPER SIDE BRACKET RH	SERVICEABLE	35.00	-
1	HEADLAMP ASSY RH	SCRATCHED	2,110.30	2,110.30
1	FRT FOG LAMP GRILLE	SERVICEABLE	93.45	-
1	FRT FENDER EMBLEM	SERVICEABLE	26.60	-
1	FRT FENDER LH	DENTED	588.80	588.80
1	FRT WHEEL CAP	SCRATCHED	346.40	346.40
	LESS 20% DISCOUNT		-814.43	-609.10
			3,257.72	2,436.40
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		1,100.00	700.00
	SPRAY PAINT.		600.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
			1,800.00	1,270.00
	GRAND TOTAL		5,057.72	3,706.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC22010683/Nqcm4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.