

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4909L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER CENTRE MOULDIG	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING	SERVICEABLE	155.00	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER REFLECTOR RH	CRACKED	41.45	41.45
1	REAR BUMPER SIDE UDR CVR RH	SERVICEABLE	108.00	-
1	REAR FENDER RH	DENTED	1,768.30	1,768.30
1	REAR BLIND SPOT RADAR RH	SERVICEABLE	1,784.40	-
1	TAILLAMP RH	CRACKED	935.40	935.40
	LESS 20% DISCOUNT		-1,224.00	-735.56
			4,896.00	2,942.24
	NETT ITEMS			
1	REVERSE SENSOR (N)	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-18.00	-
			162.00	-
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	LABOUR			
	PANEL BEATING.		1,200.00	700.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
	CHECK LIGHTINGS.		80.00	30.00
	TUFF KOTE.		100.00	40.00
	DIAGNOSTIC & RESET REAR BLIND SPOT RADAR RH.	NOT NECESSARY	350.00	-

Report Ref No. NS/INC22010684/Nvce2



## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEE. (NPA)		-	-
			2,750.00	1,300.00
	GRAND TOTAL		7,858.00	4,292.24

RECOMMENDED COST OF LUMP SUM REPAIRS		3,450.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22010684/Nvce2

**MUHAMMAD NAZRIL BIN ABDULLAH** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**