7/26/23, 4:24 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22010685/KCY3E2

Date: 26/07/2023

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001778191

Claimant Vehicle PRESONT

No: FBT594Z Insured Vehicle No: FBH5679T

Date of Loss: 25/07/2022 Nature of Claim: TP Claim No: 280910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBT594Z

Make & Model: YAMAHA MT-03 ABS (MTN320-A), 321cc Engine No: H405E0042430

Reg. Date: 20/10/2021 (Man. Year: 2021) Chassis No: MH3RH12R2MK002667

Colour: Grey Odometer: 14787 km

Engine Capacity: 321 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 140/70 R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-------------------|------------|------------|------------|--------|
| Parts | | 4,283.00 | 2,669.70 | 1,613.30 | 37.67 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 2,500.00 | 335.00 | 2,165.00 | 86.60 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Nett Amount (S\$) | 6,783.00 | 3,004.70 | 3,778.30 | 55.70 |

INSPECTION

Date of Assignment: 27/10/2022

Date Inspected: 04/11/2022 Inspected At: 60 Jalan Lam Huat #04-53

Singapore 737869

Win Automotive Services

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

7/26/23, 4:24 PM

Part Source: (Last Synchronised: 26 Jul 2023)

Parts: N/A YAMAHA MT-03 ABS (MTN320-A) 321cc (Model not available in database)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for FBT594Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|-------|-----------------------|----------------------------|-----------------------------------|------------|------------|
| 1 | 1 | *RADIATOR ASSY | Bent / Punctured | 450.00 F | *450.00 FL |
| 2 | 2 | *GUIDE AIR 1 | Dented | 60.00 F | *60.00 FL |
| 3 | 2 | *DUCT AIR | Dented | 125.00 F | *125.00 FL |
| 4 | 1 | *BRACKET 1 | Dented | 65.00 F | *65.00 FL |
| 5 | 1 | *HANDLE BAR | Bent | 155.00 F | *155.00 FL |
| 6 | 2 | *END GRIP | Dented | 88.00 F | *88.00 FL |
| 7 | 1 | *LEVEL HOLDER ASSY LH | Dented | 155.00 F | *155.00 FL |
| 8 | 1 | *SHIFT PEDAL ASSY | Bent | 135.00 F | *135.00 FL |
| 9 | 1 | *FOOTREST | Dented | 85.00 F | *85.00 FL |
| 10 | 1 | *BOLT | Necessary | 50.00 F | *50.00 FL |
| 11 | 1 | *COVER, CRANKCASE 1 | Dented | 160.00 F | *160.00 FL |
| 12 | 1 | *GASKET, COVER CRANKCASE 1 | Dented | 50.00 F | *50.00 FL |
| 13 | 1 | *MUFFLER ASSY 1 | Dented / Cut | 655.00 F | *655.00 FL |
| 14 | 1 | *CAST WHEEL FRONT | Serviceable | 595.00 F | *- FL |
| 15 | 1 | *REAR FOOT RACK | Serviceable | 250.00 F | *- FL |
| 16 | 1 | *FRONT FOOT RACK | Serviceable | 225.00 F | *- FL |
| 17 | 1 | *SIDE STAND | Repair | 220.00 F | *- FL |
| 18 | 1 | *SET COVER | Cracked | 700.00 F | *700.00 FL |
| 19 | 1 | *4T10W50 OIL | Necessary | 60.00 FS | *30.00 FS |
| F=Fra | inchise part. S=SpcNe | ett. L=ListItemDisc. | | | |
| | | | Sub Total (S\$) | 4,283.00 | 2,963.00 |
| | | - List Item Disco | ount on L Items 0.00/10.00% (S\$) | 0.00 | 293.30 |
| | | | Total Parts (S\$) | 4,283.00 | 2,669.70 |
| | | | | | |

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------|---|------------------|------------|--------|
| Labo | our Items | | | |
| 1 | SUPPLY PAINT MATERIAL TO THE REAR AND EXPANDABLE ITEMS | New | 800.00 | 0.00 |
| 2 | CARRY OUT BODY CAVITY PRESERVATION | New | 120.00 | 0.00 |
| 3 | TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PAN BEAT | New EL | 800.00 | 200.00 |
| 4 | ALIGNMENT OF FORK | New | 420.00 | 120.00 |
| 5 | CHECK WIRING | New | 60.00 | 15.00 |
| 6 | REMOVE AND REINSTALL EXHAUST MUFFLE | New | 150.00 | 0.00 |
| 7 | RESETTING / CLEAR FAULT CODE | New | 150.00 | 0.00 |
| | Gross Lab | oour Cost (S\$) | 2,500.00 | 335.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >