

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 3214A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER }	DENTED / DEFORMED	1,800.00	907.80
1	REAR BUMPER LOWER }		560.00	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	107.00	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	107.00	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	89.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	89.00	-
1	REAR BUMPER GARNISH	DENTED	460.00	266.90
1	REAR REFLECTOR LH	NOT NECESSARY	250.00	-
1	REAR REFLECTOR RH	NOT NECESSARY	250.00	-
	LESS 5% DISCOUNT		-185.60	-58.74
			3,526.40	1,115.96
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE W/GARNISH (SN)	NOT NECESSARY	90.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	48.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	100.00	-
			288.00	-
	<u>LABOUR</u>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	100.00	-
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	50.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS.		1,000.00	150.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			2,470.00	400.00
	GRAND TOTAL		6,284.40	1,515.96

Report Ref No. CS/LPC22010694/Uwy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/LPC22010694/Uwy3e2

CHUA KANG SENG

Licensed Appraiser