

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010699/UPA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800125698
Claimant Vehicle No :	EY3553K	Insured Vehicle No :	SMF861X
Date of Loss:	27/10/2022	Nature of Claim:	TP
		Claim No:	2884168188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY3553K	Engine No:	G4FGJU205575
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Chassis No:	KMHD841CMJU704449
Reg. Date:	19/06/2018 (Man. Year: 2018)	Odometer:	58225 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,650.16	6,766.40	4,883.76	41.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	1,890.00	2,680.00	58.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,220.16	8,656.40	7,563.76	46.63
Approved Total (Overridden) (S\$)		6,900.00		
Nett Amount (S\$)	16,220.16	6,900.00	9,320.16	57.46
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
Nett Liability (S\$)		7,798.80		

INSPECTION

Date of Assignment:	28/10/2022		
Date Inspected:	28/10/2022	Inspected At:	Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390 Singapore 408700
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR	Badly Dented	1,993.20 FL	*1,832.00 FL
2	1		*FRONT DOOR SIDE MIRROR	Repair	638.60 FL	*- FL
3	2		*FRONT DOOR HINGES	Not Necessary	42.20 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	96.00 FL	*- FL
5	1		*FRONT DOOR REGULATOR	Shorted	350.40 FL	*350.40 FL
6	1		*FRONT DOOR OUTER TOP MOULDING	Not Necessary	25.20 FL	*- FL
7	1		*FRONT RIGHT FENDER	Badly Dented	1,227.70 FL	*1,227.70 FL
8	1		*FRONT FENDER INNER SHIELD	Torn	95.70 FL	*95.70 FL
9	10		*FRONT FENDER INNER SHIELD INNER CLIPS	Necessary	50.00 FL	*50.00 FL
10	1		*FRONT FENDER LOWER MUDFLAP	Deformed	31.00 FL	*31.00 FL
11	1		*FRONT BUMPER	Torn	974.40 FL	*474.40 FL
12	1		*FRONT BUMPER SIDE HOLDER	Cracked	38.00 FL	*38.00 FL
13	10		*FRONT BUMPER INNER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*FRONT TOW COVER	Not Necessary	21.00 FL	*- FL
15	1		*FRONT RIGHT FROG LAMP	Cracked	365.10 FL	*365.10 FL
16	1		*FRONT RIGHT TOP LAMP	Cracked	198.00 FL	*198.00 FL
17	1		*FRONT FROG LAMP OUTER COVER	Twisted	115.40 FL	*115.40 FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	695.80 FL	*695.80 FL
19	1		*FRONT BUMPER SIDE BRACKET	Bent	38.00 FL	*38.00 FL
20	1		*HEADLAMP RIGHT	Cracked	1,198.80 FL	*1,198.80 FL
21	1		*WIRPER TANK	Deformed	67.50 FL	*67.50 FL
22	1		*FRONT DOOR PILLAR	Repair	998.00 FL	*- FL
23	1		*FRONT WINDSCREEN OUTER RUBBER	Not Necessary	57.10 FL	*- FL
24	1		*FRONT WINDSCREEN TAPE FOAM	Not Necessary	42.10 FL	*- FL
25	1		*FRONT WINDSCREEN SUNX STICKER	Not Necessary	300.00 FL	*- FL
26	1		*FRONT WINDSCREEN INNER SEALANT	Not Necessary	120.00 FL	*- FL
27	1		*SPORT RIM (O/S)	Cut	300.00 FL	*300.00 FL
28	1		*SHOCK ABSORBER (O/S)	Bent	745.00 FL	*355.00 FL
29	1		*LOWER ARM (O/S)	Bent	452.90 FL	*344.20 FL
30	1		*FRONT KNUCKLE ARM (O/S)	Bent	396.00 FL	*396.00 FL
31	1		*FRONT HUP ARM (O/S)	No such part	321.00 FL	*- FL
32	1		*FRONT KNUCKLE ARM BEARING (O/S)	Damaged	160.00 FL	*160.00 FL
33	1		*DRIVE SHAFT RIGHT (O/S)	Not Necessary	936.70 FL	*- FL
34	1		*STEERING RACK & OPION	Not Necessary	1,046.90 FL	*- FL
35	1		*SET DOOR VISION (ASSESSOR)	Necessary	300.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,487.70	8,443.00
- List Item Discount on L Items 20.00/20.00% (S\$)	2,837.54	1,676.60
Total Parts (S\$)	11,650.16	6,766.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOWING ACCIDENT PLACE & IDAC	New	180.00	50.00
2	TO RUSTPROOF	New	100.00	60.00
3	TO REMOVE/REFIT WINDSCREEN	New	140.00	0.00
4	TO DISMANTLE /RENEW DOOR	New	200.00	60.00
5	TO REMOVE/REFIT DASHBOARD	New	300.00	0.00
6	TO DISMANTLE /RENEW UNDERCARRIAGE	New	200.00	120.00
7	TO COMPUTER WHEEL ALIGNMENT BEFORE AND AFTER	New	150.00	100.00
8	TO DISMANTLE /RENEW ACCIDENT PORTION	New	1,800.00	600.00
9	TO SPRAY PAINT	New	1,500.00	900.00
Gross Labour Cost (\$\$)			4,570.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >