



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7465U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	568.20	568.20
2	REAR BUMPER REFLECTOR @\$156.20	NOT NECESSARY	312.40	-
1	REAR BUMPER SIDE LH	DEFORMED	195.40	195.40
2	REAR BUMPER SIDE RETAINER @\$57.00	N/S DAMAGED	114.00	57.00
1	REAR FENDER AIR VENT LH	NOT NECESSARY	89.60	-
1	REAR FENDER COWLING LH	NOT NECESSARY	150.20	-
2	REAR FENDER ARCED GARNISH @\$184.70	N/S CUT	369.40	184.70
1	TAIL LAMP LH	CRACKED	475.00	475.00
1	BUZZER	NOT NECESSARY	109.00	-
1	REAR FLOOR PANEL BOTTOM GARNISH	NOT NECESSARY	269.00	-
	LESS 20% DISCOUNT		-530.44	-296.06
			2,121.76	1,184.24
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	40.00	10.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			660.00	40.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,000.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	100.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-

Report Ref No. CS/INC22010703/Aqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			2,780.00	300.00
GRAND TOTAL			5,561.76	1,524.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,200.00

Report Ref No. CS/INC22010703/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.