



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

INCOME INSURANCE LTD
75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557
ATTN: AZHARI AFIDI

Ref: CS3/INC22010704/Tcy3e2
Date: 08/12/2022
Code: INC

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|---------------------|------------------------|-----------------------|------------|
| Insured Veh. | SML 703M | Veh. Inspected | SBW 7924T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1194384-001 | Excess (\$) | 0.00 |
| Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | 27/10/2022 |


2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------------------|---------------------|------------|
| Make & Model | MERCEDES BENZ 200E | c.c | 1998 |
| Engine No. | HIDDEN | Year of Reg. | 1993 |
| Chassis No. | WDB1240192B898203 | Colour | BLACK |
| Odometer | 352902 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|---------|---------|
| R/H Front Tyre | 225/45 R17 | PIRELLI | 6 mm |
| L/H Front Tyre | 225/45 R17 | PIRELLI | 6 mm |
| R/H Rear Tyre | 225/45 R17 | PIRELLI | 6 mm |
| L/H Rear Tyre | 225/45 R17 | PIRELLI | 6 mm |

4. Description of Damages

| | |
|--|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. |  |
|--|---|

5. General Information

| | | | |
|-----------------------|--|----------------------------|-------------------------|
| Accident Date | 26/10/2022 | Inspect Date / Time | 27/10/2022 (12:59 PM) |
| Survey held at | RS GARAGE SERVICES PTE LTD BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875 | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

Report Ref No. CS3/INC22010704/Tcy3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.