11/24/22, 10:36 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**ECICS Limited** Our File No: CS/ICS22010712/UNY3Q2

10 Eunos Road 8, #09-04A Singapore Post Centre Date: 24/11/2022 Singapore 408600

**REFERENCE** 

Insured/Claimant: TAN CHUN HIAN KENNY Policy No: MPC22A00136100

Date of Loss: 23/10/2022 Nature of Claim: OD Claim No: DMPC2200504H/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SNF8532G

Make & Model: MERCEDES-BENZ CLA200, 1.6 (R18) (A) Engine No: 27091030312971 Reg. Date: Chassis No: 09/01/2014 (Man. Year: 2013) WDD1173432N058668

Colour: Black Odometer: 107174 km

**Engine Capacity:** 1595 cc Market Value/New Car Price: S\$34,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm Front Right Side: Rear Right Side: Dunlop 7 mm Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,702.00	6,721.00	2,981.00	30.73
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,210.00	980.00	230.00	19.01
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculate	ed Gross Total (S\$)	10,912.00	7,701.00	3,211.00	29.43
Approved Total	al (Overridden) (S\$)		6,150.00		
	- Excess (S\$)	0.00	1,100.00	-1,100.00	
	(S\$)	10,912.00	5,050.00	5,862.00	53.72
+ 0	SST 7.00/7.00% (S\$)	763.84	353.50	410.34	53.72
	Nett Amount (S\$)	11,675.84	5,403.50	6,272.34	53.72

**INSPECTION** 

Date of Assignment: 27/10/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)

SME Motor Pte Ltd (Kaki Bukit)

28/10/2022 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Date Inspected:

Singapore 417883 Estimated Period of Repair: 4.0 days

MARCUS CHUA **HUEY YON** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

		•			
$oldsymbol{-}$	$\triangle$ 1		$r \circ$	n	$\sim$
ı 🔪	ᄃ	$\Box$	ᆫ		ce

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2022)

Parts: 143 MERCEDES-BENZ CLA200 1.6 (R18) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SNF8532G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Torn	1,300.00 F	*1,300.00 F
2	1		*FRT BUMPER LOWER GRILLE	Torn	160.00 F	*160.00 F
3	10		*FRT BUMPER CLIP	Necessary	40.00 F	*40.00 F
4	1		*FRT BUMPER LOWER SIDE TRIM RH	Torn	85.00 F	*85.00 F
5	1		*INTERCOOLER	Punctured / Dented	650.00 F	*650.00 F
6	1		*FRT BUMPER UNDER COVER	Torn	260.00 F	*260.00 F
7	1		*ENGINE UNDER COVER	Torn	195.00 F	*195.00 F
8	2		*FRT FENDER INNER COWLING FRT JOI	NT Torn	300.00 F	*300.00 F
9	2		*FRT SHOCK ABSORBER	Not Necessary	1,000.00 F	*- F
10	1		*FRT LOWER ARM	N/S Cut / O/S Not Necessary	700.00 F	*350.00 F
11	1		*FRT KNUCKLE ARM	N/S Bent / O/S Not Necessary	1,300.00 F	*650.00 F
12	1		*FRT KNUCKLE BEARING	N/S Damaged/ O/S Not Necessary	760.00 F	*380.00 F
13	1		*STEERING CROSSMEMBER	Dented / Bent	1,100.00 F	*1,100.00 F
14	1		*FRT BUMPER LOWER BEAM	Not Necessary	330.00 F	*- F
Sup	<u>pleme</u>	entary #1				
15	1		*STEERING CROSSMEMBER BRACKET	LH Dented	155.00 F	*155.00 F
16	2		*BODY UNDER COVER	Torn	370.00 F	*370.00 F
17	1		*INTERCOOLER GARNISH	Torn	115.00 F	*115.00 F
F=Fra	nchise	part.				
				Sub Total (S\$)	8,820.00	6,110.00
				+ Margin on L,N Items 10.00/10.00% (S\$)	882.00	611.00
				Total Parts (S\$)	9,702.00	6,721.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX 2 FRT UNDERCARRIAGE (WITH CROSSMEMBER)	New	350.00	300.00
3	4 WHEEL ALIGNMENT	New	80.00	60.00
4	LABOUR CHARGE	New	500.00	400.00
5	SPRAY PAINTING	New	250.00	200.00
	Gross Labou	r Cost (S\$)	1,210.00	980.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >