



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 8822E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	2,271.23	2,271.23
1	LH/R BUMPER GARNISH (SN)	NECESSARY	137.59	137.59
1	RH/R BUMPER GARNISH (SN)	NECESSARY	137.59	137.59
1	REAR BUMPER BOTTOM PANEL (SN)	DEFORMED	610.00	610.00
1	CT/R BUMPER BOTTOM PANEL GARNISH (SN)	CRACKED	138.38	138.38
1	RH/R BUMPER BOTTOM PANEL GARNISH (SN)	CRACKED	178.62	178.62
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	155.06	-
1	LH/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	102.22	-
1	RH/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	102.60	-
4	CT/R PARKING SENSOR @\$195.43 (SN)	NOT NECESSARY	781.72	-
4	CT/R PARKING SENSOR SEAL @\$7.10 (SN)	NOT NECESSARY	28.40	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	1,352.69	-
			5,996.10	3,473.41
LABOUR				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT.			480.00	480.00
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.			1,440.00	960.00
RESPRAY REAR BUMPER.			1,000.00	800.00
			2,920.00	2,240.00
GRAND TOTAL			8,916.10	5,713.41
RECOMMENDED COST OF REPAIRS				5,713.41

Report Ref No. CS/SMR22010717/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.