

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22010718/EWY3Q2  
**Date:** 22/11/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00072972200	
Claimant Vehicle No: SLV5094M	Insured Vehicle No: YQ7103E	
Date of Loss: 26/10/2022	Nature of Claim: TP	Claim No: SNM22D207687/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLV5094M</b>	
Make & Model: NISSAN SYLPHY, 1.6 CVT (A)	Engine No: HR16913549C
Reg. Date: 29/12/2017 (Man. Year: 2017)	Chassis No: MNTBBAB17Z0030395
Colour: Grey	Odometer: 42965 km
Engine Capacity: 1598 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/50 R15	Rear Tyre Size: 215/50 R15
Front Left Side: Michelin 4 mm	Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm	Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,849.30	2,033.50	815.80	28.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	1,840.00	1,050.00	36.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,739.30</b>	<b>3,873.50</b>	<b>1,865.80</b>	<b>32.51</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,100.00</b>		
	5,739.30	3,100.00	2,639.30	45.99
<b>+ GST 7.00/7.00% (\$\$)</b>	401.75	217.00	184.75	45.99
<b>Nett Amount (\$\$)</b>	<b>6,141.05</b>	<b>3,317.00</b>	<b>2,824.05</b>	<b>45.99</b>

### INSPECTION

Date of Assignment: 28/10/2022	
Date Inspected: 07/11/2022	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair: 7.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
<b>Parts:</b>	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV5094M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY RH	Broken	388.00 FL	*388.00 FL
2	1		*SIDE MIRROR COVER RH	Missing	90.00 FL	*90.00 FL
3	1		*REAR DOOR RH	Repair	1,016.00 FL	*- FL
4	1		*REAR DOOR WINDOW PILLAR TOP STICKER RH	Not Necessary	39.00 FL	*- FL
5	1		*REAR DOOR WINDOW PILLAR SIDE STICKER RH	Not Necessary	39.00 FL	*- FL
6	1		*REAR DOOR HANDLE BAR (LONG)	Cut	284.00 FL	*284.00 FL
7	1		*REAR DOOR HANDLE BAR (SHORT)	Cut	52.00 FL	*52.00 FL
8	1		*REAR FENDER RH	Dented	1,533.00 FL	*1,533.00 FL
9	1		*TAIL LAMP RH	Broken	359.00 FL	*359.00 FL
10	1		*TAIL LAMP CLIPS RH	Broken	5.00 FL	*5.00 FL
11	1		*PUMP FUEL COVER	Dented	94.00 FL	*94.00 FL
12	1		*FRONT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR FENDER RH SEALANT	Necessary	60.00 FS	*30.00 FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,019.00</b>	<b>2,875.00</b>
<b>- List Item Discount on L Items 30.00/30.00% (S\$)</b>	1,169.70	841.50
<b>Total Parts (S\$)</b>	<b>2,849.30</b>	<b>2,033.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	700.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	100.00	100.00
5	TO REMOVE AND REPLACE REAR DOOR RH FITTING,TRIMMINGS, GARNISH ,WINDOW GLASS AND LOCK MECHANISM	New	120.00	0.00
6	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ELECTRICAL PROPER FUNCTION	New	90.00	30.00
7	TO REMOVE AND REFIT REAR SEAT IN ORDER TO REPAIR	New	100.00	50.00
8	TO REMOVE AND REFIT ROOTS LINING & UPHOLSTERY GARNISH	New	100.00	50.00
9	TO REMOVE AND REFIX REAR QUARTER GLASS RH	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,890.00</b>	<b>1,840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >