



Your Ref : SNM22D207348/C02/KOHNGLH

Date: 01st Nov 2022

Our Ref : CS/CTI22010724/Uny3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJH 7591D

INSURED VEHICLE: PC 3069C

ACCIDENT ON 11/10/2022

Instruction was received to inspect the vehicle Reg. No. SJH 7591D. The inspection was conducted on 31/10/2022 at the premises of M/s Hock Wah Motor Workshop Pte Ltd. 3011 Bedok Industrial Park E #01-2008, Singapore 489977.

The following vehicle information was recorded:

Registration Number	: SJH 7591D
Make/Model	: Honda Fit 1.3G A
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: GE61096367
Engine Capacity	: 1339 cc

The vehicle sustained damages at the rear and front portion. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 7,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,757.00
Nett Liability	<u>S\$ 4,243.00</u>

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.