

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010725/TVY3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00060592201
Claimant Vehicle No :	SLF1850H	Insured Vehicle No :	XE6423M
Date of Loss:	28/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207734/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF1850H	Engine No:	4GR0516953
Make & Model:	TOYOTA LEXUS, 2.5 IS250 (A)	Chassis No:	JTHBK262605086763
Reg. Date:	14/01/2009 (Man. Year: 2008)	Odometer:	255147 km
Colour:	Grey		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,366.51	13,556.37	8,810.14	39.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,710.00	1,960.00	53.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,036.51	15,266.37	10,770.14	41.37
Approved Total (Overridden) (S\$)		12,200.00		
(S\$)	26,036.51	12,200.00	13,836.51	53.14
+ GST 8.00/8.00% (S\$)	2,082.92	976.00	1,106.92	53.14
Nett Amount (S\$)	28,119.43	13,176.00	14,943.43	53.14

INSPECTION

Date of Assignment:	28/10/2022	
Date Inspected:	01/11/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
Parts:	143	TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1850H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,759.00 FL	*1,759.00 FL
2	1		*BONNET RH HINGE	Bent	129.00 FL	*129.00 FL
3	1		*BONNET LH HINGE	Bent	129.00 FL	*129.00 FL
4	1		*BONNET LOCK	Not Necessary	235.00 FL	*- FL
5	1		*BONNET INSULATOR	Deformed	218.00 FL	*218.00 FL
6	1		*FRONT BUMPER	Deformed	987.10 FL	*881.00 FL
7	1		*FRONT BUMPER NUMBER PLATE	Deformed	187.00 FL	*187.00 FL
8	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	329.40 FL	*- FL
9	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	89.10 FL	*- FL
10	1		*FRONT BUMPER RH FOG LAMP SIDE COVER	Not Necessary	55.30 FL	*- FL
11	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	329.40 FL	*- FL
12	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	89.10 FL	*- FL
13	1		*FRONT BUMPER LH FOG LAMP SIDE COVER	Not Necessary	55.30 FL	*- FL
14	1		*FRONT BUMPER RH SIDE RETAINER	Deformed	68.00 FL	*68.00 FL
15	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	68.00 FL	*- FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	478.00 FL	*- FL
17	1		*FRONT BUMPER INNER SPONGE	Not Necessary	158.90 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	189.20 FL	*- FL
19	1		*FRONT BUMPER TOWING COVER	Not Necessary	31.10 FL	*- FL
20	1		*FRONT BUMPER UPPER RUBBER SEAL	Not Necessary	165.60 FL	*- FL
21	1		*FRONT GRILLE	Deformed	602.00 FL	*602.00 FL
22	1		*FRONT GRILLE EMBLEM	Necessary	118.30 FL	*118.30 FL
23	1		*FRONT AIR DUCT	Not Necessary	113.50 FL	*- FL
24	1		*RH HEADLAMP	Cracked	2,188.00 FL	*2,188.00 FL
25	1		*RH HEADLAMP LOWER BRACKET	Not Necessary	141.30 FL	*- FL
26	1		*LH HEADLAMP	Cracked	2,188.00 FL	*2,188.00 FL
27	1		*LH HEADLAMP LOWER BRACKET	Not Necessary	141.30 FL	*- FL
28	1		*FRONT BRACE PANEL	Not Necessary	92.30 FL	*- FL
29	1		*SUPPORT PANEL	Bent	1,296.50 FL	*1,296.50 FL
30	1		*SUPPORT PANEL TOP COVER	Deformed	304.50 FL	*304.50 FL
31	2		*HORNS	Not Necessary	215.70 FL	*- FL
32	1		*AIRCON CONDENSER	Bent	1,205.00 FL	*1,205.00 FL
33	1		*RADIATOR ASSY	Cracked	1,518.00 FL	*1,518.00 FL
34	1		*RADIATOR FAN ASSY	Cracked	1,309.00 FL	*701.00 FL
35	1		*FRONT RH FENDER	Bent	970.00 FL	*970.00 FL
36	1		*FRONT RH FENDER SPLASH SHIELD	Not Necessary	278.00 FL	*- FL
37	1		*FRONT LH FENDER	Repair	970.00 FL	*- FL
38	1		*FRONT LH FENDER SPLASH SHIELD	Not Necessary	278.00 FL	*- FL
39	1		*AIRCON CONDENSER	Not Necessary	1,281.60 FL	*- FL
40	1		*RADIATOR ASSY	Not Necessary	1,673.80 FL	*- FL
41	1		*RADIATOR FAN ASSY	Not Necessary	971.60 FL	*- FL
42	1		*SET BONNET INSULATION CLIPS	Necessary	90.00 FS	*30.00 FS
43	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
45	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
46	1		*SET SUPPORT PANEL TOP COVER CLIPS	Not Necessary	70.00 FS	*- FS

Report was unsubmitted during this print-out.

5/16/23, 1:13 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
48	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
49	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
50	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*40.00 FS
51	1		*AIR FILTER COVER	Cracked	467.00 FL	*467.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					24,773.90	15,049.30
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,407.39	1,492.93
Total Parts (\$\$)					22,366.51	13,556.37
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	40.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	30.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR	New	280.00	100.00
6	REMOVE AND REPLACE RADIATOR ASSY AND HOSES TO ASSIST REPAIR	New	280.00	100.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	100.00	40.00
8	DIAGNOSE AND RESET CONTROL UNIT	New	450.00	0.00
Gross Labour Cost (\$\$)			3,670.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >