



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 122X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP RH	BROKEN	9,892.00	3,555.76
1	HEAD LAMP LOWER BRACKET RH	NOT NECESSARY	250.00	-
1	BONNET	NOT NECESSARY	3,933.00	-
1	FRONT FENDER RH	DENTED	1,672.00	763.20
1	FRONT FENDER INNER SHIELD RH	TORN	201.00	117.00
1	FRONT WHEEL BEARING RH	NOT NECESSARY	395.00	-
1	FRONT WHEEL BEARING HUB RH	NOT NECESSARY	499.00	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	1,239.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	785.00	-
1	FRONT UPPER ARM RH	NOT NECESSARY	699.00	-
1	FRONT CONTROL ARM RH	NOT NECESSARY	592.00	-
1	FRONT THRUST ARM RH	NOT NECESSARY	782.00	-
1	FRONT ABSORBER RH	NOT NECESSARY	1,164.00	-
1	FRONT STABILIZER LINK RH	NOT NECESSARY	359.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	510.00	-
1	FRONT TIE ROD RH	NOT NECESSARY	310.00	-
1	FRONT TIE ROD END RH	NOT NECESSARY	882.00	-
1	STEERING RACK & PINION ASSY	NOT NECESSARY	3,190.00	-
1	DRIVE SHAFT RH	NOT NECESSARY	2,492.00	-
1	FRONT BUMPER	CUT / DENTED	2,015.00	1,716.80
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	184.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	629.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	839.00	-
1	FRONT BUMPER NOZZLE COVER RH	NOT NECESSARY	203.00	-
1	FRONT BUMPER NOZZLE PUMP RH	NOT NECESSARY	422.00	-
1	FRONT BUMPER FOG LAMP GARNISH RH	NOT NECESSARY	310.00	-
1	FRONT BUMPER FOG LAMP OUTER GARNISH RH	NOT NECESSARY	294.00	-
1	WIPER WASHER TANK	NOT NECESSARY	392.00	-
1	WIPER WASHER TANK MOTOR	NOT NECESSARY	349.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	2,633.00	-

Report Ref No. CS/AGI22010726/Dny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-3,811.60	-615.28
			34,304.40	5,537.48
	<u>SPECIAL NETT ITEMS</u>			
1	HEAD LAMP CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	20.00
1	FRONT BUMPER FOG LAMP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT FENDER CAT STICKER LIMITED EDITION (SN)	NOT FITTED	300.00	-
1	FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	15.00
1	FRONT BUMPER LOWER SKIRTING (SN)	CUT	1,500.00	800.00
1	SPORT RIM (SN)	CUT	2,000.00	1,000.00
1	TYRE (SN)	NOT NECESSARY	800.00	-
			4,800.00	1,835.00
	<u>LABOUR</u>			
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS.		1,000.00	600.00
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS .		1,000.00	600.00
	TO TUFF COAT DAMAGED AREAS .		200.00	30.00
	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS .	NOT NECESSARY	400.00	-
	TO RNR AIRCON CONDENSER AND TOP UP AIRCON GAS.	NOT NECESSARY	150.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		120.00	60.00
	TO CHECK & REFIX ALL ELECTRICAL WIRINGS.		200.00	30.00
	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS.		300.00	150.00
			3,370.00	1,470.00
	GRAND TOTAL		42,474.40	8,842.48



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00
---	--	--	-----------------

Report Ref No. CS/AGI22010726/Dny3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.