

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4061Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	55.80	-
1	FRONT BUMPER	TORN	481.10	481.10
1	FRONT BUMPER GRILLE RH	CUT	186.50	186.50
1	FRONT BUMPER MOULDING CENTRE UPPER	NOT NECESSARY	368.50	-
1	FRONT DAY LIGHT RH	NOT NECESSARY	642.50	-
1	FRONT FENDER SHIELD RH	NOT NECESSARY	164.70	-
1	HEAD LAMP RH	NOT NECESSARY	2,110.30	-
1	FRONT FENDER RH	BENT	588.80	588.80
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT WHEEL COVER	CUT	346.40	346.40
	LESS 20% DISCOUNT		-994.24	-325.88
			3,976.96	1,303.52
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER ADVERTISEMENT (SN)	CUT	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.		700.00	350.00
	SPRAY PAINT.		600.00	500.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	TOWING FEE.		60.00	-
			1,420.00	850.00
GRAND TOTAL			5,496.96	2,253.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,800.00

Report Ref No. NS/INC22010729/Tncq2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.