



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3646S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER BLUE -DRIVE LH	NECESSARY	26.60	26.60
1	FRT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	FRT WHEEL CAP LH	CUT	346.40	346.40
1	WING MIRROR LH	TO REPAIR SEE LABOUR	1,391.70	-
	LESS 20% DISCOUNT		-503.64	-74.60
			2,014.56	298.40
	<u>NETT ITEMS</u>			
1	FRONT DR COMFORTDELGRO LH (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING-FRONT DOOR LH.INCLUSIVE OF THE REPAIR OF WING MIRROR LH AND FRT FENDER LH .		800.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	30.00
			1,460.00	1,055.00
	GRAND TOTAL		3,542.06	1,420.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,150.00

Report Ref No. NS/INC22010730/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.