

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010731/TVY3E2**Date:** 31/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00006672201

**Claimant Vehicle
No :** SMU4359A**Insured Vehicle
No :** SLV6134A

Date of Loss: 27/10/2022

Nature of Claim: TP

Claim
No: SNM22D207720/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMU4359A**

Make & Model: HONDA SHUTTLE, 1.5 G CVT SENSING (A)

Engine No: LEB7138003

Reg. Date: 13/08/2020 (Man. Year: 2019)

Chassis No: GP72106542

Colour: Grey

Odometer: 65773 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: INTERTRAC 6 mm

Rear Left Side: INTERTRAC 6 mm

Front Right Side: INTERTRAC 6 mm

Rear Right Side: INTERTRAC 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,606.80	7,863.60	21,743.20	73.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,240.00	2,340.00	6,900.00	74.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,846.80	10,203.60	28,643.20	73.73
Approved Total (Overridden) (S\$)		8,100.00		
Nett Amount (S\$)	38,846.80	8,100.00	30,746.80	79.15

INSPECTION

Date of Assignment: 01/11/2022

Date Inspected: 28/10/2022 Inspected At:

PROMPT AUTO SOLUTIONS PTE LTD (Premier)
8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT SENSING (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4359A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,272.00 FL	*1,193.00 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	155.00 FL	*155.00 FL
3	1		*TAILGATE CENTRE EMBLEM	Necessary	46.00 FL	*46.00 FL
4	1		*TAILGATE SHUTTLE EMBLEM	Necessary	58.00 FL	*58.00 FL
5	1		*TAILGATE CHROME MOULDING GARNISH	Deformed	331.00 FL	*331.00 FL
6	1		*TAILGATE RH LAMP ASSY	Cracked	442.00 FL	*442.00 FL
7	1		*TAILGATE RH LAMP GASKET	Necessary	25.00 FL	*25.00 FL
8	1		*TAILGATE LH LAMP ASSY	Cracked	442.00 FL	*442.00 FL
9	1		*TAILGATE LH LAMP GASKET	Necessary	25.00 FL	*25.00 FL
10	1		*TAILGATE LOCK	Bent	181.00 FL	*181.00 FL
11	1		*TAILGATE LOCK CATCH	Not Necessary	45.00 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed	354.00 FL	*354.00 FL
13	1		*TAILGATE WEATHERSTRIP	Twisted	189.00 FL	*189.00 FL
14	1		*TAILGATE PULL HANDLE	Deformed	32.00 FL	*32.00 FL
15	1		*TAILGATE WIPER MOTOR	Not Necessary	432.00 FL	*- FL
16	1		*TAILGATE RH NUMBER PLATE LAMP	Not Necessary	34.00 FL	*- FL
17	1		*TAILGATE LH NUMBER PLATE LAMP	Not Necessary	34.00 FL	*- FL
18	1		*TAILGATE RH DAMPER	Not Necessary	223.00 FL	*- FL
19	1		*TAILGATE LH DAMPER	Not Necessary	223.00 FL	*- FL
20	1		*TAILGATE RH HINGE	Not Necessary	94.00 FL	*- FL
21	1		*TAILGATE LH HINGE	Not Necessary	94.00 FL	*- FL
22	1		*REAR BUMPER	Deformed	1,153.00 FL	*936.00 FL
23	1		*REAR BUMPER TOWING COVER	Deformed	32.00 FL	*32.00 FL
24	1		*REAR BUMPER RH REFLECTOR	Not Necessary	64.00 FL	*- FL
25	1		*REAR BUMPER RH REFLECTOR GARNISH	Not Necessary	58.00 FL	*- FL
26	1		*REAR BUMPER RH INNER SPONGE	Not Necessary	98.00 FL	*- FL
27	1		*REAR BUMPER LH REFLECTOR	Cracked	64.00 FL	*64.00 FL
28	1		*REAR BUMPER LH REFLECTOR GARNISH	Not Necessary	58.00 FL	*- FL
29	1		*REAR BUMPER LH INNER SPONGE	Cracked	98.00 FL	*98.00 FL
30	1		*REAR BUMPER RH SIDE RETAINER	Deformed	42.00 FL	*42.00 FL
31	1		*REAR BUMPER LH SIDE RETAINER	Deformed	42.00 FL	*42.00 FL
32	1		*REAR BUMPER RH BRACKET	Not Necessary	57.00 FL	*- FL
33	1		*REAR BUMPER LH BRACKET	Not Necessary	57.00 FL	*- FL
34	1		*REAR BUMPER RH LOWER COVER	Not Necessary	112.00 FL	*- FL
35	1		*REAR BUMPER LH LOWER COVER	Not Necessary	112.00 FL	*- FL
36	1		*END PANEL (OUTER)	Bent	567.00 FL	*567.00 FL
37	1		*END PANEL (INNER)	Bent	487.00 FL	*487.00 FL
38	1		*END PANEL BUZZER SENSOR	Cracked	167.00 FL	*167.00 FL
39	1		*END PANEL ANTENNA SENSOR	Not Necessary	98.00 FL	*- FL
40	1		*RH TAILLAMP ASSY	Cut	558.00 FL	*510.50 FL
41	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	44.00 FL	*- FL
42	1		*RH TAILLAMP PANEL	Not Necessary	198.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LH TAILLAMP ASSY	Cut	558.00 FL	*510.50 FL
44	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	44.00 FL	*- FL
45	1		*LH TAILLAMP PANEL	Not Necessary	198.00 FL	*- FL
46	1		*REAR RH FENDER	Repair	1,010.00 FL	*- FL
47	1		*REAR RH FENDER GLASS WITH RUBBER MOULDING	Not Necessary	578.00 FL	*- FL
48	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	505.00 FL	*- FL
49	1		*REAR RH FENDER SPLASH SHIELD	Not Necessary	72.00 FL	*- FL
50	1		*REAR LH FENDER	Repair	1,010.00 FL	*- FL
51	1		*REAR LH FENDER GLASS WITH RUBBER MOULDING	Not Necessary	578.00 FL	*- FL
52	1		*REAR LH FENDER INNER TRIM BOARD	Deformed	505.00 FL	*505.00 FL
53	1		*REAR LH FENDER SPLASH SHIELD	Not Necessary	72.00 FL	*- FL
54	1		*REAR COMPARTMENT PANEL	Repair	1,180.00 FL	*- FL
55	1		*REAR COMPARTMENT PANEL TRAY BOX	Cracked	488.00 FL	*488.00 FL
56	1		*REAR COMPARTMENT TRAY BOX COVER	Cracked	321.00 FL	*321.00 FL
57	1		*REAR COMPARTMENT FOLDABLE TOP COVER	Not Necessary	655.00 FL	*- FL
58	1		*REAR COMPARTMENT INNER SPONGE	Deformed	489.00 FL	*489.00 FL
59	1		*REAR COMPARTMENT TOP COVER BOARD	Deformed	585.00 FL	*585.00 FL
60	1		*EXHAUST SILENCER	Not Necessary	756.00 FL	*- FL
61	1		*EXHAUST SILENCER GASKET	Not Necessary	34.00 FL	*- FL
62	1		*HYBRID BATTERY	Not Necessary	15,736.00 FL	*- FL
63	1		*SET TAILGATE CHROME MOULDING GARNISH CLIPS }	Necessary	70.00 FS	*30.00 FS
64	1		*SET TAILGATE INNER TRIM BOARD CLIPS }		70.00 FS	*- FS
65	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
66	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
67	1		*TAILGATE REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
68	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
69	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
70	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
71	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
72	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
73	1		*END PANEL (OUTER) JOINT SEAL	Necessary	80.00 FS	*40.00 FS
74	1		*END PANEL(INNER) JOINT SEAL	Not Necessary	70.00 FS	*- FS
75	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
76	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
77	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
78	1		*REAR COMPARTMENT PANEL JOINT SEAL	Not Necessary	100.00 FS	*- FS
79	1		*REAR LH FENDER JOINT SEAL	Not Necessary	80.00 FS	*- FS
80	1		*REAR LH FENDER GLASS SEALANT	Not Necessary	70.00 FS	*- FS
81	1		*REAR LH FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS
82	1		*REAR RH FENDER JOINT SEAL	Not Necessary	80.00 FS	*- FS
83	1		*REAR RH FENDER GLASS SEALANT	Not Necessary	70.00 FS	*- FS
84	1		*REAR RH FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,461.00	9,727.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,854.20	1,863.40
Total Parts (\$\$)	29,606.80	7,863.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES ON AFFECTED AREAS AND REPLACED PARTS AS LISTED	New	2,800.00	800.00
2	RE-SPRAY AFFECTED AREAS AND PARTS	New	2,200.00	1,000.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	150.00	40.00
4	APPLY ANTI RUST CHEMICAL COATING	New	220.00	40.00
5	REPLACE TAILGATE WINDSCREEN GLASS TO REPAIR	New	230.00	120.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO REPAIR	New	150.00	30.00
7	REMOVE AND REPLACE RAER BUMPER REVERSE SENSORS TO REPAIR	New	100.00	30.00
8	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO REPAIR	New	480.00	80.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	200.00	0.00
10	RESET AND DIAGNOSE FAULT CODE AND SYSTEM	New	550.00	0.00
11	REMOVE AND REPLACE REAR RH FENDER GLASS TO REPAIR	New	180.00	0.00
12	REMOVE AND REPLACE REAR LH FENDER GLASS TO REPAIR	New	180.00	0.00
13	REMOVE, CHECK AND REPLACE HYBRID BATTERY TO REPAIR	New	1,200.00	200.00
14	MOUNT VEHICLE ON CHASSIS BENCH TO REPAIR AND STRAIGHTEN CHASSIS FRAME	New	600.00	0.00
Gross Labour Cost (S\$)			9,240.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >