

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010733/UQY3Q2**Date:** 03/11/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle No : SGD3005M **Insured Vehicle No :** GBH2363H

Date of Loss: 26/10/2022 Nature of Claim: TP Claim No: 2022 22007727FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGD3005M**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZZ143875

Reg. Date: 08/12/2015 (Man. Year: 2015) Chassis No: MHFBT9F3006036035

Colour: Silver Odometer: 21336 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,377.55	2,398.40	5,979.15	71.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,230.00	2,630.00	68.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,237.55	3,628.40	8,609.15	70.35
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	12,237.55	2,900.00	9,337.55	76.30
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/10/2022

Date Inspected: 28/10/2022 Inspected At: Imperium Automotive - Kaki Bukit (HQ)
25 Kaki Bukit Road 4, #01-49 Synergy@KB
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD3005M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	892.00 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	131.00 FL	*- FL
3	1		*FRONT HEADLAMP -RH	Broken	1,149.00 FL	*656.30 FL
4	1		*FRONT GRILLE	Cracked	477.00 FL	*221.10 FL
5	1		*FRONT GRILLE LOGO	Necessary	89.50 FL	*75.00 FL
6	1		*FRONT BUMPER	Distorted	586.00 FL	*533.90 FL
7	1		*FRONT BUMPER CENTRE GRILLE	Twisted / Torn	269.00 FL	*214.20 FL
8	1		*FRONT BUMPER FOG LAMP	Cracked	516.00 FL	*405.10 FL
9	1		*FRONT BUMPER FOG LAMP COVER	Twisted	135.00 FL	*135.00 FL
10	1		*FRONT BUMPER LOWER MOULDING	Not Necessary	130.20 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Repair	399.00 FL	*- FL
12	1		*FRONT BUMPER UNDER COVER	Not Necessary	275.20 FL	*- FL
13	1		*FRONT BUMPER SIDE RETAINER	O/S Cracked	98.00 FL	*75.50 FL
14	1		*FRONT BUMPER CHROME MOULDINGS	O/S Cracked	350.00 FL	*145.00 FL
15	1		*FRONT FENDER (O/S)	Repair	399.50 FL	*- FL
16	1		*FRONT FENDER INNER SHIELD (O/S)	Torn	160.50 FL	*160.50 FL
17	1		*FRONT FENDER BRACKET	Not Necessary	83.60 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Repair	1,162.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed /Twisted	285.00 FL	*285.00 FL
20	1		*FRONT BRACE PANEL	Not Necessary	145.00 FL	*- FL
21	1		*FRONT WIPER TANK	Deformed	263.30 FL	*184.60 FL
22	1		*FRONT WIPER MOTOR	Not Necessary	189.50 FL	*- FL
23	1		*FRONT WHEEL HUB WITH BEARING	Not Necessary	355.90 FL	*- FL
24	1		*FRONT SHOCK ABSORBER	Not Necessary	360.80 FL	*- FL
25	1		*FRONT KNUCKLE ARM	Not Necessary	560.50 FL	*- FL
26	1		*FRONT LOWER ARM	Not Necessary	300.90 FL	*- FL
27	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
28	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	45.00 FS	*40.00 FS
29	1		*FRONT TYRE	Not Necessary	350.00 FS	*- FS
30	1		*FRONT WHEEL RIM -RH	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,818.40	3,171.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,440.85	772.80
Total Parts (\$\$)	8,377.55	2,398.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	300.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
4	TO APPLY UNDERCOATING	New	200.00	0.00
5	PANEL BEATING	New	1,600.00	550.00
6	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	600.00
Gross Labour Cost (S\$)			3,860.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >