

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010735/UWY3M4**Date:** 10/11/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2002102115
Claimant Vehicle No : SLU393M **Insured Vehicle No :** XE4410M
 Date of Loss: 27/10/2022 Nature of Claim: TP Claim No: 2022 22007731KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU393M**
 Make & Model: MERCEDES-BENZ E250, 2.0 AVG (R18 LED) (A) Engine No: 27492031192883
 Reg. Date: 21/11/2017 (Man. Year: 2017) Chassis No: WDD2130452A323824
 Colour: Black Odometer: 86278 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 275/40 R18
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,346.13	12,312.40	9,033.73	42.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	2,540.00	1,580.00	38.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,466.13	14,852.40	10,613.73	41.68
Approved Total (Overridden) (\$\$)		11,800.00		
Nett Amount (\$\$)	25,466.13	11,800.00	13,666.13	53.66
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 28/10/2022
 Date Inspected: 28/10/2022 Inspected At: Yew Hok Auto Services (HQ)
 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Nov 2022)

Parts: 143 MERCEDES-BENZ E250 2.0 AVG (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU393M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,532.47 FL	*1,874.00 FL
2	1		*REAR BUMPER REFLECTOR - LH	Cracked	89.71 FL	*89.71 FL
3	2		*REAR BUMPER PDC SENSORS	Shorted	565.52 FL	*565.52 FL
4	2		*REAR BUMPER PDC SENSOR HOLDERS	Necessary	51.00 FL	*51.00 FL
5	2		*REAR BUMPER PDC SENSOR RINGS	Necessary	17.00 FL	*17.00 FL
6	1		*REAR BUMPER DIFUSSER	Not Necessary	421.43 FL	*- FL
7	1		*REAR BUMPER CHROME MOULDING	Not Necessary	291.42 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	871.59 FL	*871.59 FL
9	2		*REAR BUMPER TOP HOLDERS - L/R	Cracked	153.82 FL	*153.82 FL
10	2		*REAR BUMPER SIDE HOLDERS - L/R	Cracked	164.38 FL	*164.38 FL
11	1		*REAR BUMPER SIDE CARRIERS - L/R (2PCS)	N/s Cracked	300.12 FL	*150.06 FL
12	1		*REAR BUMPER PDC SENSOR WIRE HARNESS	Not Necessary	411.23 FL	*- FL
13	1		*REAR FENDER - LH	Distorted	2,889.63 FL	*2,889.63 FL
14	1		*REAR FENDER AIR VENT	Not Necessary	68.75 FL	*- FL
15	1		*REAR FENDER UNDERCOVER	Torn	188.23 FL	*188.23 FL
16	1		*REAR FENDER SOUND GENERATOR UNIT	Cracked	691.63 FL	*691.63 FL
17	1		*REAR FENDER INNER TRIM	Not Necessary	481.92 FL	*- FL
18	1		*REAR TAILLAMP - LH	Broken	971.93 FL	*971.93 FL
19	1		*REAR TAILLAMP PANEL - LH	Bent	292.70 FL	*292.70 FL
20	1		*REAR SPORT WHEEL - LH	Warped	1,055.90 FL	*1,055.90 FL
21	1		*REAR SHOCK ABSORBER - LH	Not Necessary	645.33 FL	*- FL
22	1		*REAR SPRING LINK ARM	Twisted	386.57 FL	*386.57 FL
23	1		*REAR STRUT ARM	Twisted	281.26 FL	*281.26 FL
24	1		*REAR TORSION BAR LINKAGE	Not Necessary	193.06 FL	*- FL
25	1		*REAR TIE ROD ARM	Twisted	248.41 FL	*248.41 FL
26	1		*REAR AXLE SHAFT - LH	Not Necessary	2,827.80 FL	*- FL
27	1		*REAR CAMBER ARM	Twisted	273.26 FL	*273.26 FL
28	1		*REAR WHEEL HUB BEARING	Damaged	514.73 FL	*514.73 FL
29	1		*REAR WHEEL CARRIER	Warped	1,829.56 FL	*1,488.00 FL
30	1		*REAR WINDSHIELD	Not Necessary	1,223.21 FL	*- FL
31	1		*REAR END PANEL	Repair	1,662.13 FL	*- FL
32	1		*REAR TYRE - LH (LOCAL PURCHASE) (350) (70%)	Cut	650.00 FS	*245.00 FS
33	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
34	1		*SET REAR WINDSHIELD REPAIR KIT	Necessary	180.00 FS	*50.00 FS
35	1		*SET REAR FENDER INSULATION	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,605.70	13,634.33
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,259.57	1,321.93
Total Parts (\$\$)	21,346.13	12,312.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
3	TO REMOVE, REFIX REAR UNDERCARRIAGE	New	350.00	150.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	100.00
5	TO RESPRAY UNDERCOATING	New	120.00	50.00
6	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	100.00
7	TO DIAGNOS, ERASE FAULT MEMORY AFTER REPAIR	New	450.00	200.00
8	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
9	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,120.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >