

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22010736/TCY3Q2**Date:** 10/01/2023**REFERENCE**

|                   |                         |                  |                            |
|-------------------|-------------------------|------------------|----------------------------|
| Insured/Claimant: | TJOENG NGIAN KHIN ALLEN | Policy No:       | DMPG22007334               |
| Date of Loss:     | 25/10/2022              | Nature of Claim: | OD Claim No: CDMPG22002298 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJX6414E</b>                   | Engine No:  | 1NZY101101        |
| Make & Model:               | TOYOTA VIOS, 1.5 (A)              | Chassis No: | MR053HY9305168365 |
| Reg. Date:                  | 29/06/2010 (Man. Year: 2010)      | Odometer:   | 268048 km         |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 1497 cc                           |             |                   |
| Market Value/New Car Price: | S\$26,000.00                      |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 185/60 R15  | Rear Tyre Size:  | 185/60 R15  |
| Front Left Side:  | Falken 6 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 8,509.00          | 4,252.42          | 4,256.58          | 50.02         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 4,930.00          | 2,950.00          | 1,980.00          | 40.16         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>13,439.00</b>  | <b>7,202.42</b>   | <b>6,236.58</b>   | <b>46.41</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>5,750.00</b>   |                   |               |
| <b>- Excess (\$\$)</b>                    | 800.00            | 800.00            | 0.00              | 0.00          |
| <b>Nett Amount (\$\$)</b>                 | <b>12,639.00</b>  | <b>4,950.00</b>   | <b>7,689.00</b>   | <b>60.84</b>  |

**INSPECTION**

|                             |                          |                                                                                                               |
|-----------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 28/10/2022               | Lkt Group Pte Ltd (HQ)<br>Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi<br>Industrial Estate<br>Singapore 408700 |
| Date Inspected:             | 28/10/2022 Inspected At: |                                                                                                               |
| Estimated Period of Repair: | 9.0 days                 |                                                                                                               |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                       |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                       |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 09 Jan 2023)         |
| Parts:        | 143                                                                                                                                                                          | TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                     |
| Print Code:   | (Unsubmitted, no print-code for SJX6414E)                                                                                                                                    |                                                       |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                       |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                       |

Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *ROOF PANEL                               | Repair        | 870.30 FL   | *- FL        |
| 2   | 2   |          | *ROOF PANEL SIDE MOULDING                 | Necessary     | 512.20 FL   | *336.00 FL   |
| 3   | 1   |          | *ROOF LINING                              | Not Necessary | 594.50 FL   | *- FL        |
| 4   | 1   |          | *FRONT WINDSCREEN                         | Cracked       | 1,430.00 FL | *1,070.20 FL |
| 5   | 1   |          | *FRONT WINDSCREEN PILLAR RH (NPA)         | Repair        | 0.00 FL     | *- FL        |
| 6   | 1   |          | *FRONT WINDSCREEN PILLAR INNER GARNISH RH | Not Necessary | 141.70 FL   | *- FL        |
| 7   | 1   |          | *FRONT WINDSCREEN PILLAR LH (NPA)         | Repair        | 0.00 FL     | *- FL        |
| 8   | 1   |          | *FRONT WINDSCREEN MOULDING                | Necessary     | 176.45 FL   | *120.00 FL   |
| 9   | 1   |          | *IU BRACKET                               | Necessary     | 25.00 FL    | *25.00 FL    |
| 10  | 1   |          | *REAR VIEW MIRROR                         | Broken        | 212.64 FL   | *212.64 FL   |
| 11  | 1   |          | *REAR WINDSCREEN MOULDING                 | Not Necessary | 138.00 FL   | *- FL        |
| 12  | 1   |          | *FRONT WIPER GARNISH RH                   | Cut           | 75.82 FL    | *75.82 FL    |
| 13  | 1   |          | *FRONT WIPER GARNISH LH                   | Not Necessary | 75.82 FL    | *- FL        |
| 14  | 1   |          | *BONNET                                   | Bent          | 821.00 FL   | *821.00 FL   |
| 15  | 1   |          | *FRONT BUMPER                             | Repair        | 745.30 FL   | *- FL        |
| 16  | 2   |          | *FRONT BUMPER SIDE RETAINER               | Not Necessary | 248.00 FL   | *- FL        |
| 17  | 2   |          | *FRONT BUMPER BRACKET                     | Not Necessary | 141.00 FL   | *- FL        |
| 18  | 1   |          | *HEADLAMP RH                              | Cracked       | 680.40 FL   | *543.90 FL   |
| 19  | 1   |          | *FRONT FENDER RH                          | Bent          | 674.90 FL   | *581.40 FL   |
| 20  | 1   |          | *FRONT FENDER EMBLEM VVTI RH              | Necessary     | 82.60 FL    | *82.60 FL    |
| 21  | 1   |          | *FRONT DOOR RH                            | Bent          | 773.60 FL   | *773.60 FL   |
| 22  | 1   |          | *FRONT DOOR BLACK TAPE RH                 | Necessary     | 97.30 FL    | *97.30 FL    |
| 23  | 1   |          | *FRONT DOOR LH (NPA)                      | Repair        | 0.00 FL     | *- FL        |
| 24  | 1   |          | *FRONT DOOR BLACK TAPE LH                 | Not Necessary | 97.30 FL    | *- FL        |
| 25  | 1   |          | *WING MIRROR ASSY RH                      | Broken        | 475.00 FL   | *475.00 FL   |
| 26  | 1   |          | *REAR DOOR RH (NPA)                       | Repair        | 0.00 FL     | *- FL        |
| 27  | 1   |          | *REAR DOOR BLACK TAPE RH                  | Not Necessary | 94.00 FL    | *- FL        |
| 28  | 1   |          | *REAR FENDER RH (NPA)                     | Repair        | 0.00 FL     | *- FL        |
| 29  | 1   |          | *BOOTLID (NPA)                            | Repair        | 0.00 FL     | *- FL        |
| 30  | 1   |          | *BOOTLID LOGO                             | Necessary     | 95.40 FL    | *95.40 FL    |
| 31  | 1   |          | *BOOTLID EMBLEM VIOS                      | Necessary     | 78.20 FL    | *78.20 FL    |
| 32  | 1   |          | *BOOTLID EMBLEM J                         | Necessary     | 68.50 FL    | *68.50 FL    |
| 33  | 1   |          | *REAR BUMPER (NPA)                        | Repair        | 0.00 FL     | *- FL        |
| 34  | 2   |          | *REAR BUMPER SIDE RETAINER                | Not Necessary | 240.40 FL   | *- FL        |
| 35  | 1   |          | *SUNDRIES                                 | Not Necessary | 60.00 FS    | *- FS        |
| 36  | 1   |          | *SET FRONT BUMPER CLIPS                   | Not Necessary | 80.00 FS    | *- FS        |
| 37  | 1   |          | *SET REAR BUMPER CLIPS                    | Not Necessary | 80.00 FS    | *- FS        |
| 38  | 1   |          | *FRONT DOOR INNER SEAL RH                 | Not Necessary | 100.00 FS   | *- FS        |
| 39  | 1   |          | *SET FRONT DOOR TRIMBOARD CLIPS RH        | Not Necessary | 65.00 FS    | *- FS        |
| 40  | 1   |          | *FRONT DOOR INNER SEAL LH                 | Not Necessary | 100.00 FS   | *- FS        |
| 41  | 1   |          | *SET FRONT DOOR TRIMBOARD CLIPS LH        | Not Necessary | 65.00 FS    | *- FS        |
| 42  | 1   |          | *REAR DOOR INNER SEAL RH                  | Not Necessary | 100.00 FS   | *- FS        |
| 43  | 1   |          | *SET REAR DOOR TRIMBOARD CLIPS RH         | Not Necessary | 60.00 FS    | *- FS        |
| 44  | 1   |          | *REAR FENDER INNER TRIM CLIPS RH          | Not Necessary | 70.00 FS    | *- FS        |
| 45  | 1   |          | *FRONT WINDSCREEN PRIMER & CLEANER        | Necessary     | 100.00 FS   | *60.00 FS    |
| 46  | 1   |          | *FRONT WINDSCREEN SEALANT                 | Necessary     | 80.00 FS    | *60.00 FS    |

Report was unsubmitted during this print-out.

1/10/23, 8:06 AM

Adjuster Report

| No.                                                 | Qty | Part No. | Particulars                        | Condition     | Repairer's | Amount    |
|-----------------------------------------------------|-----|----------|------------------------------------|---------------|------------|-----------|
| 47                                                  | 1   |          | *FRONT WINDSCREEN INNER SEAL       | Necessary     | 60.00 FS   | *40.00 FS |
| 48                                                  | 1   |          | *FRONT WINDSCREEN PRIMER & CLEANER | Not Necessary | 100.00 FS  | *- FS     |
| 49                                                  | 1   |          | *FRONT WINDSCREEN SEALANT          | Not Necessary | 80.00 FS   | *- FS     |
| 50                                                  | 1   |          | *FRONT WINDSCREEN INNER SEAL       | Not Necessary | 60.00 FS   | *- FS     |
| F=Franchise part. S=SpcNett. L=ListItemDisc.        |     |          |                                    |               |            |           |
| Sub Total (\$\$)                                    |     |          |                                    |               | 10,925.33  | 5,616.56  |
| - List Item Discount on L Items 25.00/25.00% (\$\$) |     |          |                                    |               | 2,416.33   | 1,364.14  |
| Total Parts (\$\$)                                  |     |          |                                    |               | 8,509.00   | 4,252.42  |
| Report was unsubmitted during this print-out.       |     |          |                                    |               |            |           |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                         | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                     |          |                 |                 |
| 1                               | PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA | New      | 1,750.00        | 1,000.00        |
| 2                               | CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT    | New      | 80.00           | 30.00           |
| 3                               | TO R&R FRONT WINDSCREEN FOR REPLACEMENT PARTS       | New      | 150.00          | 120.00          |
| 4                               | TO R&R REAR WINDSCREEN FOR PREPLACEMENT PARTS       | New      | 150.00          | 0.00            |
| 5                               | TO R&R INTERIOR UPHOLSTERY FOR REPLACEMENT PARTS    | New      | 200.00          | 100.00          |
| 6                               | TO APPLY UNDERCOATING FOR RUST ROOFING              | New      | 200.00          | 100.00          |
| 7                               | SPRAY PAINTING ON ACCIDENT AREA                     | New      | 2,400.00        | 1,600.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                     |          | <b>4,930.00</b> | <b>2,950.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >