

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2300969

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SPRINGLEAF TOWER SINGAPORE 079909 INV Date 18/02/2023

Reference CC6/CTI22010740/Kpa3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 2833J

Insured Veh. GBF 1638Z

Claim No. SNM22D207771/C02

Policy No. DMCVSNA00004972202

Accident Date 26/10/2022

Inspection Date 27/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CC6/CTI22010740/Kpa3q2			
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date:	18/02/2023			
			Code:	СТІ			
1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBF 1638Z	Veh. Inspected	SMG 2833J			
	Policy No.	DMCVSNA00004972202	Coverage (\$)	0.00			
	Claim No.	SNM22D207771/C02	Excess (\$)	0.00			
	Assign From		Assign Date	27/10/2022			
2.		Vehicle Partic	culars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496			
	Engine No.	HIDDEN	Year of Reg.	2018			
	Chassis No.	GK81203173	Colour	METALLIC GREY			
	Odometer	72168 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	205/45 ZR16	PETLAS	7 mm			
	L/H Front Tyre	205/45 ZR16	PETLAS	7 mm			
	R/H Rear Tyre	205/45 ZR16	PETLAS	7 mm			
	L/H Rear Tyre	205/45 ZR16	PETLAS	7 mm			
4.		Description	on of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.				
	DAMAGES SEE DI	ETAILS.					
5.		General	I Information				
	Accident Date	26/10/2022	Inspection Date	27/10/2022			
	Survey held at	ALAN'S UNITED AUTO PTE LTD)				
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642					
5a.		Re	emarks				
Ju.		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		CE TO YOUR INSTRUCTIONS, W					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2833J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	BENT	1,193.40	1,193.40
1	TAIL GATE OUTER CHROME	SERVICEABLE	383.00	-
2	TAIL GATE LAMP @\$340.80	N/S CUT	681.60	340.80
1	TAIL GATE INNER LOCK	DENTED	256.00	256.00
1	TAIL GATE RUBBER	SERVICEABLE	168.00	-
1	TAIL GATE 'SHUTTLE' EMBLEM	NECESSARY	55.00	55.00
2	TAIL GATE GLASS SIDE MOULDING @\$56.50	NECESSARY	113.00	113.00
1	TAIL GATE GLASS LOWER MOULDING	NECESSARY	86.20	86.20
1	TAIL GATE INNER TRIM COVER	SERVICEABLE	220.00	-
1	TAIL GATE OPEN POCKET	SERVICEABLE	25.00	-
2	TAILLAMP @\$520.50	N/S CUT	1,041.00	520.50
1	REAR END PANEL	TO REPAIR SEE LABOUR	458.20	-
1	END PANEL TOP GARNISH	SERVICEABLE	155.50	-
1	TOOLS COMPARTMENT TRAY	SERVICEABLE	165.00	-
1	REAR BUMPER FASCIA	BURST	1,150.40	985.00
2	REAR BUMPER SIDE RETAINER @\$23.50	SERVICEABLE	47.00	-
2	REAR BUMPER REFLECTOR SPONGE @\$38.70	SERVICEABLE	77.40	-
1	REAR BUMPER TOW COVER	SERVICEABLE	22.50	-
	LESS 20% DISCOUNT		-1,259.64	-709.98
			5,038.56	2,839.92
	SPECIAL NETT ITEMS			
1	REAR BUMPER LOWER SPOILER (SN)	CRACKED	400.00	400.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR NO PLATE WITH BOX (SN)	SERVICEABLE	50.00	-
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
			1,110.00	640.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00

Report Ref No. CC6/CTI22010740/Kpa3q2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

4,759.92

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET .		120.00	60.00
	TO APPLY UNDERSEALING.	NOT NECESSARY	60.00	-
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	600.00
	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	500.00
			2,030.00	1,280.00
	GRAND TOTAL		8,178.56	4,759.92

Report Ref No. CC6/CTI22010740/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 2833J

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 2833J

RE-INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 2833J

RE-INSPECTION



