

Acc. Rec. By:

REF:

CCG/CTA 22010745/Dp2

ASSIGNMENT

CDE Jan 2029

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 10 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STD 6727G Yr Regn: Jan / 2021

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA

Eng/No: G4LEKU422021

C/No: KMHC851CVLW192851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/10/2022 D.O.I. 31/10/2022

Survey held at S. Prust Sin Mung

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/5 Frnt 7 4/5 Rear 7 0/5 Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Taping SMU 7989L

BV calculation attached in file for record purpose. Do not indicate in survey report.

No wheel alignment as front left wheel and rear right wheel physically out of alignment

14/3/23 found 4/5 30,000/- with 14 days of rep

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Format: _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Inve (\$ _____)

Others _____

REPAIR ESTIMATE

INSURANCE: China Taping

VEHICLE NO.: SHD 6727 G

Description	Qty	List Price	Amount
Front Fender(LH) <i>Dent</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel side support (LH) <i>HH</i>	1	\$ 238.80	\$ 238.80
Front Fender Apron Panel (LH) <i>HH</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH) <i>HH</i>	1	\$ 329.00	\$ 329.00
Front Fender Shield (LH) <i>tooth</i>	1	\$ 164.70	\$ 164.70
Frt Door(LH) <i>Dent</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>SC</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH) <i>mostly broken</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH <i>HH</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH) <i>HH</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH) <i>HH</i>	1	\$ 153.70	\$ 153.70
Front Door Check (LH) <i>HH</i>	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (LH) <i>HH</i>	1	\$ 385.60	\$ 385.60
Front Door Mirror ASSY (LH) <i>tooth</i>	1	\$ 1,691.70	\$ 1,691.70
Front Door Protector(LH) <i>crack</i>	1	\$ 186.20	\$ 186.20
Front Door Outer Moulding (LH) <i>SC</i>	1	\$ 110.10	\$ 110.10
Frt Safety Belt(Assy)(LH/RH) <i>actuated</i>	2	\$ 648.90	\$ 1,297.80
Rear Safety Belt(Assy)(LH/RH) <i>actuated</i>	2	\$ 513.20	\$ 1,026.40
Rear Safety Belt Garnish Cover(LH/RH) <i>mostly broken</i>	2	\$ 398.00	\$ 796.00
Rocker Panel Outer Garnish <i>crack/Dent</i>	1	\$ 715.60	\$ 715.60
Rocker Panel Outer <i>HH</i>	1	\$ 1,799.60	\$ 1,799.60
Rocker Panel Step Garnish (Front) (LH) <i>HH</i>	1	\$ 156.50	\$ 156.50
Front Windscreen Moulding <i>HH</i>	1	\$ 157.30	\$ 157.30
Front Windscreen Pillar Outer(LH) <i>HH</i>	1	\$ 3,764.90	\$ 3,764.90
Front Wheel Rim (LH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub assy (LH) <i>Dent</i>	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap <i>broken</i>	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(LH) <i>distorted</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 372.50	\$ 372.50
Front Drive Shaft (LH) <i>HH</i>	1	\$ 1,136.70	\$ 1,136.70
Rack & Pinion Assy <i>SC</i>	1	\$ 2,387.40	\$ 2,387.40
STG Tie Rod <i>HH</i>	1	\$ 125.60	\$ 125.60
STG Tie End <i>distorted</i>	1	\$ 94.70	\$ 94.70
Stabilizer Bar <i>distorted</i>	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link <i>distorted</i>	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (LH) <i>distorted</i>	1	\$ 596.80	\$ 596.80
Knuckle Arm (LH) <i>distorted</i>	1	\$ 663.60	\$ 663.60
Roof Upholstery lining <i>chumples</i>	1	\$ 1,983.30	\$ 1,983.30
Airbag Control Module <i>actuated</i>	1	\$ 1,243.70	\$ 1,243.70
Curtain airbag module (RH) <i>actuated</i>	1	\$ 1,344.50	\$ 1,344.50
Sensor Assy Impact -Frt Impact <i>HH</i>	1	\$ 643.90	\$ 643.90
Airbag Sensor <i>actuated</i>	1	\$ 348.10	\$ 348.10
Airbag Frt Seat <i>actuated</i>	1	\$ 1,344.50	\$ 1,344.50

Front Cushion Seat (RH) <i>toys</i>	1	\$ 5,183.20	\$ 5,183.20
Rear Bumper <i>broken</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>broken</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH) <i>Dent</i>	1	\$ 188.10	\$ 188.10
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>crack / mount</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HH</i> <i>broken</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH) <i>broken</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>WCC</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>broken</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH) <i>broken</i>	1	\$ 123.10	\$ 123.10
Rear Bumper Reflector Lamp(LH) <i>broken</i>	1	\$ 82.90	\$ 82.90
Tail Lamp(LH) <i>HH</i>	1	\$ 935.40	\$ 935.40
Tail Lamp Quarter Panel(LH) <i>HH</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>Dent</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>HH</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>HH</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>HH</i>	1	\$ 892.50	\$ 892.50
Spare Tyre Panel Cushion <i>HH</i>	1	\$ 692.50	\$ 692.50
Spare Tyre Panel UNDER SIDE PANEL (LH) <i>HH</i>	1	\$ 239.80	\$ 239.80
Panel Assy-Rear Floor Side (LH) <i>HH</i>	1	\$ 39.40	\$ 39.40
Rear tray tools box LH <i>HH</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>HH</i>	1	\$ 354.20	\$ 354.20
Exhaust Pipe Insulator <i>HH</i>	1	\$ 235.00	\$ 235.00
Exhaust Silencer <i>HH</i>	1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>HH</i>	1	\$ 29.20	\$ 29.20
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (LH) <i>SLK</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (LH) <i>HH</i>	1	\$ 165.50	\$ 165.50
Rear Fender Air-Duct (LH) <i>mounty broken</i>	1	\$ 87.30	\$ 87.30
Rear Fender Trim Board (LH) <i>HH</i>	1	\$ 788.75	\$ 788.75
Assy BSD Blind Spot Radar (LH) <i>bracket bt</i>	1	\$ 1,784.40	\$ 1,784.40
Wiring Harness BWS Ext <i>HH</i>	1	\$ 988.90	\$ 988.90
Rear Tyre Rim (LH/RH) <i>broken / distorted</i>	2	\$ 1,124.20	\$ 2,248.40
Rear Wheel Hub-Cap (LH/RH) <i>broken</i>	2	\$ 346.40	\$ 692.80
Rear Wheel Hub assy <i>Dm</i>	2	\$ 554.00	\$ 1,108.00
Rear Trailing Arm(LH/RH) <i>bt</i>	2	\$ 265.40	\$ 530.80
Rear Assist (LH/RH) <i>distorted</i>	2	\$ 227.90	\$ 455.80
Rear shock Absorber(LH/RH) <i>distorted</i>	2	\$ 230.50	\$ 461.00
Rear Shock Absorber Mounting (LH/RH) <i>HH</i>	2	\$ 133.10	\$ 266.20
Rear Absorber stopper (LH/RH) <i>HH</i>	2	\$ 137.60	\$ 275.20
Rear Absorber Cover (LH/RH) <i>HH</i>	2	\$ 175.60	\$ 351.20
Rear Crossmember <i>bt</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (LH/RH) <i>HH</i>	2	\$ 147.30	\$ 294.60
Rear Upper Arm(LH/RH) <i>distorted</i>	2	\$ 239.50	\$ 479.00
Rear Lower Arm(LH/RH) <i>distorted</i>	2	\$ 393.10	\$ 786.20
Rear Knuckle Arm (LH/RH) <i>distorted</i>	2	\$ 538.10	\$ 1,076.20
SUB TOTAL			\$ 63,672.79
LESS 20%			\$ 12,734.56
DISCOUNTED TOTAL			\$ 50,938.23

2001-SH

15,565.10

35,763.80
28,611.04

BIFROST AUTO PTE LTD

SUPPLEMENTARY

DATE: 2-Nov-22

INSURANCE: China Taiping.

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 6727 G (S)

Description	Qty	List Price	Amount
Engine Crossmember <i>distorted</i>	1	\$ 1,803.90	\$ 1,803.90
SUB TOTAL			\$ 1,803.90
LESS 20%			\$ 360.78
DISCOUNTED TOTAL			\$ 1,443.12
ESTIMATE TOTAL			\$1,443.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com

[Signature]
Jkk Auto

[Signature]