

3. RECEBY: Tau

REF:

cel / ASM 22010747 / Tpa3.

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / IF / VS / TP RES / OD RES / EVA / INV / MV

To inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 852K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG1495U Yr Regn: 2016 / Sep.

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Swift C.C. 1372

Colour: Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 78211 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JSIA FZC82500332936

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55 R16

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO, DI GT Radial

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.L. 28/10/22

Survey held at Hui Huang Hong Sao

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prelim. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

PRCS _____

Others _____

Add Fee: _____

☐ Site Insp. (4)

☐ Interview (4)

☐ T. Insp. (4)

☐ T. Insp. (4)

Transportation:

Lump Sum / 12.1.1

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921
Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbb@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

Date of survey: 28 October 2022
Motor Surveyor: LKK Auto Consultants Pte Ltd
Surveyor: Taufik

26th October 2022

Type of repair: Lump Sum

Estimate cost of repairs to Suzuki Swift - SLG 1495 U

1 pc	Tailgate	\$ 967.00	bt
1 pc	Tailgate emblem 'S'	\$ 20.00	nn
1 pc	Tailgate emblem 'Swift'	\$ 20.00	nn
1 pc	Tailgate emblem 'Suzuki'	\$ 30.00	nn
1 pc	Tailgate weatherstrip	\$ 135.00	nn
1 pc	Tailgate inner trim	\$ 180.00	x
1 pc	Tailgate lower garnish	\$ 120.00	x
1 pc	Tailgate handle	\$ 80.00	x
1 pc	Tailgate inner lock	\$ 263.00	x
1 pc	Tailgate lower catch	\$ 30.00	x
1 pc	Tailgate number plate lamp LH	\$ 30.00	x
1 pc	Tailgate number plate lamp garnish LH	\$ 50.00	x
1 pc	Tailgate rubber stopper LH	\$ 15.00	x
2 pcs	Taillamps @\$355.00	\$ 710.00	nn
2 pcs	Taillamp brackets @\$35.00	\$ 70.00	x nn
2 pcs	Taillamp lower brackets @\$35.00	\$ 70.00	x nn
1 pc	Rear bumper	\$ 890.00	de 600.15
1 pc	Rear bumper reinforcement	\$ 250.00	x nn
2 pcs	Rear bumper rear side retainers @\$25.00	\$ 50.00	x nn
2 pcs	Rear bumper side retainers @\$25.00	\$ 50.00	de
1 pc	Rear end panel	\$ 405.00	bt
1 pc	Rear end panel garnish	\$ 120.00	de
2 pcs	Rear end panel air vents @\$36.00	\$ 72.00	de
1 pc	Rear end panel antenna	\$ 75.00	x nn
1 pc	Rear end panel switch	\$ 105.00	x nn
1 pc	Rear end floor panel	\$ 250.00	buc
1 pc	Rear end floor panel board	\$ 350.00	de
2 pcs	Rear fenders @\$515.00	\$ 1,030.00	RH x R, LH buc
1 pc	Rear fender inner trim board LH	\$ 350.00	de
1 pc	Rear exhaust silencer insulator plate	\$ 65.00	bt
1 pc	Front bumper	\$ 748.00	nn 659
1 pc	Front bumper reinforcement	\$ 508.00	bt 325.20
1 pc	Front bumper absorber	\$ 260.00	nn 215
1 pc	Front bumper lower air grille	\$ 55.00	nn
1 pc	Front bumper front retainer LH	\$ 25.00	x nn
1 pc	Front bumper side retainer LH	\$ 25.00	x nn
1 pc	Front bumper fog lamp bezel LH	\$ 30.00	x nn
1 pc	Headlamp LH	\$ 594.00	nn
1 pc	Headlamp bracket LH	\$ 15.00	x XNN
1 pc	Bonnet	\$ 465.00	Rx
		\$ 9,577.00	
		\$ 1,436.55	
	Less 15%	\$ 8,140.45	

8507.35
5531.25

1 set	Tailgate inner trim clips	\$ 30.00	SN X an
1 set	Rear end side trim panel LH clips	\$ 30.00	SN ✓ NEC
1 set	Rear bumper clips	\$ 30.00	SN ✓ NEC
1 set	Rear RH fender inner shield LH clips	\$ 30.00	SN X an
1 set	Reverse sensors	\$ 250.00	SN 200nw ✓
1 pc	Windscreen sealant	\$ 60.00	SN ✓ NEC
2 sets	Number plate w/casings	\$ 120.00	SN Rear crn ✓ 45 NEC
	To remove, refix tailgate windscreen glass.	\$ 120.00	✓
	To remove, transfer & refix tailgate fittings.	\$ 80.00	60
	To remove & renew reverse sensors	\$ 80.00	30
	To remove & repair rear exhaust silencer & centre pipe	\$ 150.00	X an
	To remove, refix fuel tank to facilitate repairs.	\$ 250.00	80
	To remove and refix damaged parts, align & renew replaced parts	\$ 1,500.00	1300
	Tuff kote	\$ 160.00	50
	Wiring charges	\$ 50.00	30
	Spray painting	\$ 1,800.00	1600
		<u>\$ 12,880.45</u>	3635

Dollars : Twelve thousand eight hundred eighty dollars and forty-five cents

Taupkin 97495749
 Wv 28/10/22 02pm
 L/S Resurvey after repair
 taupkin@kanto.com
 10 days

5531.25
 3635
 9166.25
 4573.00
 10 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: