

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCX 9699M Yr Regn: 23/8/18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c. 1591Colour: Silver A/C: Insured / Std / NI / NASp. Reading 54710 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHD 841 CMJU 728733Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nferq

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 28/10/22 D.O.I. 7/11/22Survey held at ARCDes. of Damages: Front RH / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

N/K-77K

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2210-584-TG

DATE : 29-Oct-2022

VEHICLE REG. NO. : SCX9699M

VEHICLE MAKE : ELANTRA AD 1.6 GLS AT (AMS)

FOR SURVEYOR

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Door RH / DD	1	\$ 1,850.00	\$ 1,850.00
2	Front Door RH Hinge Top / DT	1	\$ 75.00	\$ 75.00
3	Front Door RH Hinge Lwr / DT	1	\$ 75.00	\$ 75.00
4	Front Door RH Checker X	1	\$ 50.00	\$ 50.00
5	Front Door Black Sticker / AK	1	\$ 40.00	\$ 40.00
6	Front Door Weatherstrip / TA	1	\$ 120.00	\$ 120.00
7	Front Door Weatherstrip Outside X	1	\$ 80.00	\$ 80.00
8	A-Pillar RH Garnish Triangle X	1	\$ 60.00	\$ 60.00
9	Side Mirror Assy RH / BR	1	\$ 750.00	\$ 750.00
10	Side Mirror Assy RH Base Cover 87660X / BR	1	\$ 60.00	\$ 60.00
11	Front Fender RH / DD	1	\$ 1,250.00	\$ 1,250.00
12	Front Fendershield RH / CRU	1	\$ 100.00	\$ 100.00
13	Front Fendershield Mudguard RH / CM	1	\$ 50.00	\$ 50.00
14	Front Bumper X	1	\$ 500.00	\$ 500.00
15	Front Bumper Retainer RH V	1	\$ 45.00	\$ 45.00
16	Front Headlamp RH X	1	\$ 1,200.00	\$ 1,200.00
Total Spare Parts				\$ 6,305.00
SPECIAL NETT				
17	Front Fendershield Clips / AK	10	\$ 3.00	\$ 30.00
18	Front Bumper Clips X	10	\$ 3.00	\$ 30.00
19	Edge sealant for New Door / AK	1	\$ 60.00	\$ 60.00
Total Special Nett				\$ 120.00
LABOUR				
20	Remove, Refit, Replace and Repair Affected Area	1	\$ 1,000.00	\$ 1,000.00
21	Spray painting RH - Front Door, Front Fender, Front Bumper, Bonnet X #1	1	\$ 1,000.00	\$ 1,000.00
22	Transfer Door Fittings and Glass to New Door	1	\$ 80.00	\$ 80.00
23	Run, Diagnose, Rectify and Reset Fault Codes	1	\$ 150.00	\$ 150.00
24	Wheel Alignment	1	\$ 70.00	\$ 70.00
25	Anti-Rust Coating	1	\$ 50.00	\$ 50.00
26	Check and Rectify Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,380.00
Amount Before Excess				\$ 8,805.00
Add GST @ 7%				616.35
Total Amount Payable				\$ 9,421.35

Estimate prepared by: Ken Guan

This is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has started. New damaged parts may not be evident on first inspection and discovered after dismantling.

LKK Auto Consultancy
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer