1/16/23, 10:45 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III22003668/GPA3Q2-1

16/01/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0003403

Claimant Vehicle SNC5684L Insured Vehicle No: SNE7440A

No:

Date of Loss: 15/04/2022 Nature of Claim: ΤP Claim No: MFL2022D0002000

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNC5684L

Make & Model: INFINITI Q30, 1.6 T PREMIUM DCT (A) **Engine No:** 27091031891617 Reg. Date: 31/05/2018 (Man. Year: 2017) Chassis No: SJKDDAH15U1059974

Odometer: Colour: Blue 68617 km

Engine Capacity: 1595 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

CONDITION OF TYRES

235/50 R18 235/50 R18 Front Tyre Size: Rear Tyre Size: Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,064.80	585.00	3,479.80	85.61
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,570.00	430.00	1,140.00	72.61
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,634.80	1,015.00	4,619.80	81.99
	Approved Total (Overridden) (S\$)		800.00		
	Nett Amount (S\$)	5,634.80	800.00	4,834.80	85.80
	+ Loss of Use (3.0 x S	60.00/day) (S\$)	180.00		
	N	ett Liability (S\$)	980.00		

INSPECTION

Date of Assignment: 20/04/2022

Carsmith Private Limited (HQ)

13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ Date Inspected: 20/04/2022 Inspected At:

CENTRE

Singapore 417807

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG **CHEW HSIAO TONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Oct 2022)

Parts: M1-SUV INFINITI Q30 1.6 T PREMIUM DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC5684L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,740.00 FL	*- FL
2	1		*REAR BUMPER RETAINER LH	Not Necessary	130.00 FL	*- FL
3	1		*REAR BUMPER RETAINER RH	Not Necessary	130.00 FL	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	889.00 FL	*650.00 FL
5	1		*TOW COVER	Not Necessary	76.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	89.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Not Necessary	89.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	509.00 FL	*- FL
9	4		*PD SENSOR	Not Necessary	700.00 FL	*- FL
10	4		*SENSOR HOLDER	Not Necessary	120.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,512.00	650.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				447.20	65.00
				Total Parts (S\$)	4,064.80	585.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	600.00	200.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONECT AND CHECK FUNCTIONS	New	100.00	0.00
3	TO REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID ,REAR BUMPER ,REAR END PANEL AND OTHER AFFECTED AREAS	New	600.00	200.00
	Gross Labour	r Cost (S\$)	1,570.00	430.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >