

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22010769/UPA3Q2**Date:** 18/02/2023**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100438949   |
| <b>Claimant Vehicle No :</b> | SLK2477U                             | <b>Insured Vehicle No :</b> | SKW9084Y     |
| Date of Loss:                | 29/10/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1003830282SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SLK2477U</b>                   | Engine No:  | L15B4030167 |
| Make & Model:               | HONDA VEZEL, 1.5 X CVT (A)        | Chassis No: | RU11110162  |
| Reg. Date:                  | 08/03/2016 (Man. Year: 2015)      | Odometer:   | 120242 km   |
| Colour:                     | Silver                            |             |             |
| Engine Capacity:            | 1496 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 215/60 R16   | Rear Tyre Size:  | 215/60 R16   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 22,308.50         | 11,213.20         | 11,095.30         | 49.74         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,450.00          | 2,010.00          | 1,440.00          | 41.74         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>25,758.50</b>  | <b>13,223.20</b>  | <b>12,535.30</b>  | <b>48.66</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>10,500.00</b>  |                   |               |
| <b>(S\$)</b>                                    | 25,758.50         | 10,500.00         | 15,258.50         | 59.24         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,803.10          | 735.00            | 1,068.10          | 59.24         |
| <b>Nett Amount (S\$)</b>                        | <b>27,561.60</b>  | <b>11,235.00</b>  | <b>16,326.60</b>  | <b>59.24</b>  |
| <b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b> |                   | 300.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>11,537.00</b>  |                   |               |

**INSPECTION**

|                             |            |                                                                                                         |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 31/10/2022 |                                                                                                         |
| Date Inspected:             | 31/10/2022 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                         |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition        | Repairer's | Amount       |
|-----|-----|----------|--------------------------------------------|------------------|------------|--------------|
| 1   | 1   |          | *BONNET                                    | Buckled          | 1,410.00 F | *892.10 FL   |
| 2   | 1   |          | *BONNET INSULATOR                          | Not Necessary    | 234.00 F   | *- FL        |
| 3   | 1   |          | *BONNET INNER RUBBER                       | Necessary        | 66.80 F    | *66.80 FL    |
| 4   | 2   |          | *BONNET HINGES                             | Serviceable      | 170.00 F   | *- FL        |
| 5   | 1   |          | *BONNET LOCK                               | Bent             | 190.00 F   | *166.50 FL   |
| 6   | 1   |          | *BONNET LOCK FRT BRACKET                   | Cracked          | 145.80 F   | *145.80 FL   |
| 7   | 1   |          | *FRONT BUMPER                              | Distorted        | 820.00 F   | *752.50 FL   |
| 8   | 1   |          | *FRONT BUMPER LOWER CENTRE GRILLE          | Twisted          | 162.30 F   | *162.30 FL   |
| 9   | 2   |          | *FRONT BUMPER SIDE RETAINERS               | Bent             | 290.00 F   | *130.00 FL   |
| 10  | 1   |          | *FRONT BUMPER LOWER SPOILER                | Deformed / Torn  | 700.00 F   | *480.00 FL   |
| 11  | 1   |          | *FRONT BUMPER UNDER COVER                  | Not Necessary    | 390.00 F   | *- FL        |
| 12  | 2   |          | *FRONT BUMPER FOG LAMPS                    | Cracked          | 960.00 F   | *654.00 FL   |
| 13  | 2   |          | *FRONT BUMPER FOG LAMP GARNISHS            | Twisted          | 360.00 F   | *290.00 FL   |
| 14  | 1   |          | *FRONT BUMPER REINFORCEMENT                | Bent             | 920.00 F   | *321.00 FL   |
| 15  | 2   |          | *FRONT BUMPER REINFORCEMENT BRACKETS       | No such part     | 510.00 F   | *- FL        |
| 16  | 1   |          | *FRONT BUMPER TOP CENTRE GRILLE            | Cracked          | 280.00 F   | *280.00 FL   |
| 17  | 1   |          | *FRONT BUMPER TOW COVER                    | Cut              | 30.00 F    | *30.00 FL    |
| 18  | 1   |          | *SET FRONT BUMPER CLIPS                    | Necessary        | 50.00 F    | *50.00 FL    |
| 19  | 1   |          | *FRONT GRILLE CHROME OUTER                 | O/S Cracked      | 380.00 F   | *115.00 FL   |
| 20  | 1   |          | *FRONT GRILLE                              | Cracked          | 860.00 F   | *485.00 FL   |
| 21  | 1   |          | *FRONT GRILLE OUTER GARNISH                | Cracked          | 445.00 F   | *385.00 FL   |
| 22  | 1   |          | *FRONT GRILLE H LOGO                       | Necessary        | 35.00 F    | *35.00 FL    |
| 23  | 2   |          | *HEADLAMPS                                 | Cracked          | 4,240.00 F | *3,718.20 FL |
| 24  | 2   |          | *HEADLAMP LOWER BRACKETS                   | Cracked          | 360.00 F   | *210.00 FL   |
| 25  | 1   |          | *FRONT SUPPORT PANEL                       | Bent             | 615.00 F   | *576.20 FL   |
| 26  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH           | Torn             | 218.00 F   | *188.20 FL   |
| 27  | 1   |          | *FRONT AIR DUCT GARNISH                    | Serviceable      | 255.00 F   | *- FL        |
| 28  | 1   |          | *AIR CON CONDENSER                         | Bent / Punctured | 1,400.00 F | *1,155.20 FL |
| 29  | 1   |          | *AIR CON CONDENSER FAN ASSY                | Not Necessary    | 455.00 F   | *- FL        |
| 30  | 1   |          | *AIR CON TEPERATURE SENSOR                 | Cracked          | 199.00 F   | *160.80 FL   |
| 31  | 2   |          | *AIR CON CONDENSER SIDE GARNISHS           | Deformed / Torn  | 332.00 F   | *296.00 FL   |
| 32  | 1   |          | *RADIATOR                                  | Bent / Punctured | 1,880.00 F | *1,649.40 FL |
| 33  | 1   |          | *RADIATOR FAN ASSY                         | Not Necessary    | 480.00 F   | *- FL        |
| 34  | 2   |          | *FRONT FENDERS                             | Repair           | 1,300.00 F | *- FL        |
| 35  | 2   |          | *FRONT FENDER INNERSHIELDS                 | Not Necessary    | 296.60 F   | *- FL        |
| 36  | 2   |          | *FRONT FENDER OUTER PROTECTORS             | Torn             | 560.00 F   | *484.00 FL   |
| 37  | 1   |          | *HORN UNIT                                 | Not Necessary    | 99.00 F    | *- FL        |
| 38  | 1   |          | *SET FRONT SUPPORT PANEL TOP GARNISH CLIPS | Necessary        | 30.00 FS   | *30.00 FS    |
| 39  | 1   |          | *SET BONNET INSULATOR CLIPS                | Not Necessary    | 30.00 FS   | *- FS        |
| 40  | 1   |          | *FRONT LICENCE PLATE                       | Broken           | 50.00 FS   | *40.00 FS    |
| 41  | 1   |          | *BOL RADIATOR COOLANT                      | Necessary        | 50.00 FS   | *20.00 FS    |
| 42  | 1   |          | *BOL AIR CON OIL                           | Necessary        | 50.00 FS   | *20.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **22,308.50** **13,989.00**  
**- List Item Discount on L Items 0.00/20.00% (\$\$)** **0.00** **2,775.80**

**Total Parts (\$\$)** **22,308.50** **11,213.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                               | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                           |          |                 |                 |
| 1                              | TO CHECK WIRING                           | New      | 50.00           | 30.00           |
| 2                              | TO RESET & REPROGRAMME DIAGNOSIS SYSTEM   | New      | 100.00          | 0.00            |
| 3                              | TO REFILL AIR CON GAS                     | New      | 120.00          | 100.00          |
| 4                              | TO MOUNT VEHICLE ON CAR O-LINER           | New      | 380.00          | 0.00            |
| 5                              | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 1,000.00        | 800.00          |
| 6                              | TO PUTTY & SPRAY PAINTING                 | New      | 1,800.00        | 1,080.00        |
| <b>Gross Labour Cost (S\$)</b> |                                           |          | <b>3,450.00</b> | <b>2,010.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >