



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDH 6888B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (N)	DEFORMED / CRACKED	1,008.00	1,008.00
2	BUMPER SIDE RETAINER @\$90.00 (N)	NOT NECESSARY	180.00	-
1	BUMPER REINFORCEMENT (N)	NOT NECESSARY	877.00	-
2	REVERSE SENSOR @\$286.00 (N)	SERVICEABLE	572.00	-
4	REVERSE SENSOR BRACKET @\$68.00 (N)	NECESSARY	272.00	272.00
	LESS 10% DISCOUNT		-290.90	-128.00
			2,618.10	1,152.00
<b>LABOUR</b>				
	TO REMOVE, REPLACE REAR BUMPER & REPAIR END PANEL.		680.00	380.00
	TO REMOVE, REFIX REVERSE SENSOR & CHECK WIRING.		200.00	50.00
	TO SPRAY PAINTING.		680.00	400.00
			1,560.00	830.00
<b>GRAND TOTAL</b>			<b>4,178.10</b>	<b>1,982.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,982.00</b>

Report Ref No. CS/LIP22010774/Uvy3e2

**NO SECOND HAND PARTS**

**MARKET VALUE: \$85,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$55,788.00=NETT VALUE: \$29,212.00**

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**