

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2581A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	1,350.00	1,350.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	520.00	-
2	REAR BUMPER REFLECTOR	NOT NECESSARY	90.00	-
2	REAR BUMPER TOW COVER	MISSING	96.00	96.00
2	REAR BUMPER RETAINER	BENT / NECESSARY	110.00	110.00
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	END PANEL	TO REPAIR SEE LABOUR	760.00	-
1	END PANEL TOP GARNISH	NOT NECESSARY	120.00	-
1	BOOT LID (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOT LID LOCK	NOT NECESSARY	110.00	-
1	REAR LOGO	NOT NECESSARY	38.00	-
1	EMBLEM - MAZDA 6	NOT NECESSARY	50.00	-
1	EMBLEM - SKYACTIV	NOT NECESSARY	55.00	-
2	REVERSE SENSOR	SHORTED / TORN	320.00	320.00
1	REAR FENDER LH (NPA) (ADDITIONAL)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA) (ADDITIONAL)	TO REPAIR SEE LABOUR	-	-
4	SENSOR HOLDER (ADDITIONAL)	NECESSARY	120.00	60.00
	COST PLUS 25%		942.25	491.50
			4,711.25	2,457.50
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, END PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH.		800.00	500.00
	TO RESPRAY AFFECTED AREAS.		800.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
	TO REPAIR REAR FENDER RH / LH. (ADDITIONAL)`		200.00	100.00

Report Ref No. CS/SMO22010796/Uny3e2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

4,047.50

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RESPRAY REAR FENDER RH / LH. (ADDITIONAL)		400.00	360.00
			2,230.00	1,590.00
	GRAND TOTAL		6,941.25	4,047.50

Report Ref No. CS/SMO22010796/Uny3e2

CHUA KANG SENG
Licensed Appraiser