

ASS. REC. BY:

REF: Asm/22010805/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Systematic

of 7036

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 857k

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 0p days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YP 5610B Yr Regn: 03, 17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)
Make: TRUZU NQR75USA 5193

Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 22163 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: JAA N1R73UH 7100103

Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F. Autline 215/75R17.5
R: _____ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / BIR / SUMI /
TOYO / YOKO or Autline

Front _____ Rear _____
R/Bal. 49 mm R/Bal. 66 mm
L/Bal. 9 mm L/Bal. 66 mm

D.O.A. 25/10/22 D.O.I. 3/11/2022
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or O/S Body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>23/2</u>	<u>488p.u Center Cab</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) Date/Time, File Return to? _____
2) _____

Days Of Repair: _____
Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:
Transportation:
S - RS. SI
Fees
Others
TOTAL

Report Format :
Lump Sum / I.B.I: (\$)

Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059
 Tel : 64847188 Fax: 64841334
 GST No. 199800703G

*Not Authorised
 Recovery Bypass
 4 days*

To: **AXA Insurance Singapore Pte Ltd**

Estimation

DATE:	27-Oct-22
D.O.A :	25-Oct-22
Your ref:	XE2776X

ISUZU 19FT - YP5610B

No.	Description	Qty	Unit Price	Amount
1	Supply four (4) pc. UV treated GRP Board for the exterior and interior of doors. <i>Bz 24</i>	24	\$ 500.00	\$ 2,000.00 <i>44</i>
2	Supply two (2) pc. 100mm thickness extruded XPS Insulation foam with a min. density of 40kg/m3 between the exterior and interior. <i>12</i>	12	\$ 720.00	\$ 1,440.00 <i>4</i>
3	Supply two (2) pc. 4ft height aluminium checker skirting for the interior of doors <i>12</i>	12	\$ 480.00	\$ 960.00 <i>4</i>
4	Supply fifteen (15) no. sealant tube <i>15</i>	15	\$ 25.00	\$ 375.00 <i>4</i>
5	Supply four (4) no. stainless steel door hinges <i>R 4</i>	4	\$ 280.00	\$ 1,120.00 <i>1</i>
6	Supply two (2) no. stainless steel recess locks c/w keys <i>Dist/21</i>	2	\$ 320.00	\$ 640.00 <i>4</i>
7	Supply eight (8) length. Door rubber gaskets <i>84</i>	8	\$ 95.00	\$ 760.00 <i>4</i>
8	Supply three (3) no. Door rubber stopper <i>Ad/3</i>	3	\$ 98.00	\$ 294.00 <i>✓</i>
9	Supply one (1) set. stainless steel door holder <i>NEC for</i>	1	\$ 90.00	\$ 90.00 <i>*✓</i>
10	Supply and paint LOGO at doors <i>1</i>	1	\$ 400.00	\$ 400.00 <i>30012</i>
11	To supply labour to - remove, refix and to renew affected parts. - reverting, adjust and realignment doors			\$ 2,400.00 <i>1100.</i>

Sub Total \$ 10,479.00

7% gst \$ 733.53

Bal amount due \$ 11,212.53

Remark: *LOSS OF USED 8 days x \$480*

84884.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____