

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22010807/AVY3E2**Date:** 09/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SMT4398S**Insured Vehicle No :** SLM987S

Date of Loss: 26/10/2022

Nature of Claim: TP

Claim No: MFL2022D0006551

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMT4398S**

Make & Model: TOYOTA ESTIMA, 2.4 (A)

Engine No: 2AZC021323

Reg. Date: 04/04/2006 (Man. Year: 2006)

Chassis No: ACR507007735

Colour: Black

Odometer: 217072 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,741.40	6,089.32	12,652.08	67.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	2,550.00	2,380.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,671.40	8,639.32	15,032.08	63.50
Approved Total (Overridden) (S\$)		6,900.00		
Nett Amount (S\$)	23,671.40	6,900.00	16,771.40	70.85

INSPECTION

Date of Assignment: 31/10/2022

Date Inspected: 27/10/2022 Inspected At:

JEC AUTO SERVICE PTE LTD (HQ)
1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT4398S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	751.10 F	*751.10 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Damaged	38.90 F	*38.90 FL
4	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	295.10 F	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	381.50 F	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	163.80 F	*- FL
7	1		*HEADLAMP LH	Cracked	2,245.10 F	*2,245.10 FL
8	1		*FRONT LH FENDER	Dented	685.90 F	*685.90 FL
9	1		*FRONT LH FENDER INNER SHIELD	Deformed	243.20 F	*243.20 FL
10	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
11	1		*FRONT LH FENDER PROTECTOR	Deformed	78.50 F	*78.50 FL
12	1		*FRONT LH FENDER PROTECTOR CLIPS	Necessary	10.00 FS	*10.00 FS
13	1		*FRONT LH FENDER INNER ENCLOSURE	Deformed	48.20 F	*48.20 FL
14	1		*AIR RESONATOR TANK	Deformed	185.20 F	*185.20 FL
15	1		*FRONT LH DOOR	Repair	1,481.40 F	*- FL
16	1		*FRONT LH DOOR OUTER PROTECTOR	Repair	689.40 F	*- FL
17	1		*FRONT LH DOOR OUTER PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
18	1		*REAR LH DOOR	Repair	1,884.20 F	*- FL
19	1		*REAR LH DOOR OUTER PROTECTOR	Repair	704.10 F	*- FL
20	1		*REAR LH DOOR OUTER PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
21	1		*REAR LH FENDER PROTECTOR	Repair	85.90 F	*- FL
22	1		*REAR LH FENDER PROTECTOR CLIPS	Not Necessary	10.00 FS	*- FS
23	1		*REAR BUMPER	Repair	780.40 F	*- FL
24	1		*REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	48.90 F	*- FL
26	1		*FRONT LH WHEEL RIM	Cut	880.00 FS	*500.00 FS
27	1		*FRONT LH TYRE	Not Necessary	380.00 FS	*- FS
28	1		*FRONT LH SHOCK ABSORBER	Bent	680.00 FS	*400.00 FS
29	1		*FRONT LH LOWER ARM	Bent	398.60 F	*398.60 FL
30	1		*FRONT LH KNUCKLE ARM	Damaged	581.60 F	*581.60 FL
31	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	321.40 F	*321.40 FL
32	1		*REAR LH WHEEL RIM	Cut	880.00 FS	*500.00 FS
33	1		*REAR LH TYRE	Not Necessary	380.00 FS	*- FS
34	1		*REAR LH SHOCK ABSORBER	Not Necessary	680.00 FS	*- FS
35	1		*REAR LH WHEEL HUB C/W BEARING	Damaged	581.40 F	*581.40 FL
36	1		*REAR AXLE BEAM	Not Necessary	2,017.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,741.40	7,629.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,539.78
Total Parts (\$\$)	18,741.40	6,089.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING	New	1,800.00	1,400.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
6	TO TRANSFER REAR DOOR FITTINGS	New	150.00	0.00
7	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	220.00
8	TO DISMANTLE REAR UNDERCARRIAGE	New	480.00	60.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			4,930.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >